

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009483/APA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900253953
Claimant Vehicle No :	SMT9725Z	Insured Vehicle No :	SFD119A
Date of Loss:	07/09/2021	Nature of Claim:	TP
		Claim No:	7811340572SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9725Z	Engine No:	R16B25520092
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650LT000058
Reg. Date:	27/07/2020 (Man. Year: 2020)	Odometer:	25626 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,859.54	540.88	4,318.66	88.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	780.00	2,970.00	79.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,609.54	1,320.88	7,288.66	84.66
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	8,609.54	1,050.00	7,559.54	87.80
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,357.45		
Global Sum Settlement (S\$)		1,350.00		

INSPECTION

Date of Assignment:	08/09/2021		
Date Inspected:	09/09/2021	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	956.40 FL	*617.50 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	112.40 FL	*28.60 FL
3	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	68.70 FL	*- FL
4	1		*REAR BUMPER LOWER	Not Necessary	486.20 FL	*- FL
5	2		*REAR BUMPER SENSOR	Not Necessary	275.60 FL	*- FL
6	1		*SET REAR BUMPER SENSOR BRACKET	Not Necessary	97.30 FL	*- FL
7	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
8	1		*REAR FENDER RH	Repair	1,086.20 FL	*- FL
9	1		*REAR FENDER INNER SHIELD RH	Not Necessary	295.80 FL	*- FL
10	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
11	1		*REAR FENDER AIR-VENT RH	Not Necessary	78.50 FL	*- FL
12	1		*REAR FENDER QUARTER GLASS W/MOULDING	Not Necessary	986.70 FL	*- FL
13	1		*REAR DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	118.50 FS	*- FS
16	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
17	1		*REAR SPORT RIM RH	Not Necessary	950.00 FS	*- FS
					Sub Total (\$\$)	5,772.30 676.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	912.76 135.22
					Total Parts (\$\$)	4,859.54 540.88

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	300.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	0.00
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	0.00
5	TO REMOVE & INSTALL REAR SPARE TYRE COMPONENTS ,TRIM & GARNISH	New	150.00	0.00
6	TO CONDUCT ALL WHEEL ALIGNMENT	New	150.00	0.00
7	TO REMOVE,REPLACE & INSTALL REAR TYRE & BALANCE	New	150.00	0.00
8	TO RE-POSITION DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
9	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
10	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			3,750.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >