

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009485/EVF3N2**Date:** 13/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070148201
<b>Claimant Vehicle No :</b>	SLK1079S	<b>Insured Vehicle No :</b>	SMW885M
Date of Loss:	04/09/2021	Nature of Claim:	TP
		Claim No:	2270587940SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLK1079S</b>	Engine No:	2ZR1765407
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206031864
Reg. Date:	05/01/2017 (Man. Year: 2016)	Odometer:	103352 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	09/09/2021	
Date Inspected:	08/09/2021	Inspected At: Kok Wang Car Grooming (HQ) 1 Soon Lee Street #06-40 Pioneer Centre Singapore 627605
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$66,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*REAR BUMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*REVERSE SENSOR	Broken	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	*Check	0.00 F	*- F
9	1		*TAILGATE	Dented	0.00 F	*- F
10	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE GARNISH	*Check	0.00 F	*- F
12	1		*TAILGATE LOCK	Bent	0.00 F	*- F
13	1		*TAILGATE RUBBER	*Check	0.00 F	*- F
14	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
15	1		*REAR WINDSCREEN RUBBER	Necessary	0.00 F	*- F
16	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >