

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009487/GTF3E2**Date:** 14/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700086735
<b>Claimant Vehicle No :</b>	SLM1522T	<b>Insured Vehicle No :</b>	SLU5988P
Date of Loss:	02/09/2021	Nature of Claim:	TP
		Claim No:	4970743135SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM1522T</b>		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC AMG LINE (R18 LED) (A)	Engine No:	27492031443237
Reg. Date:	15/04/2019 (Man. Year: 2018)	Chassis No:	WDC2533462F439846
Colour:	Black	Odometer:	34709 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	09/09/2021		
Date Inspected:	09/09/2021	Inspected At:	160 Sin Ming Drive #06-13 Sin Ming Repairer: Y2k Audio Design
Estimated Period of Repair:	4.0 days		

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$176,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Buckled	0.00 F	*- F
2	1		*FRT LH DOOR RUBBER	Necessary	0.00 F	*- F
3	1		*FRT LH DOOR STEP GARNISH	Cut	0.00 F	*- F
4	1		*REAR LH DOOR	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >