

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. DROP-ARM BARRIER

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	REPLACE OF ONE (1) UNIT OF 3 METER BOOM.}		1,600.00	1,200.00
	INCLUDE INSPECTION, ADMIN AND PROCESSING FEES.}		-	-
			1,600.00	1,200.00
	GRAND TOTAL		1,600.00	1,200.00

RECOMMENDED COST OF REPAIRS	1,200.00
-----------------------------	----------

Report Ref No. CS1/LPM21009489/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.