

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS1/CTI21009490/T1UCE2

Date: 15/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00161992100
Claimant Vehicle No : GBE6851X **Insured Vehicle No :** SLF9243H
Date of Loss: 04/09/2021 Nature of Claim: TP Claim No: SNM21D205019/C03/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE6851X**
Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KC400D055197
Reg. Date: 29/02/2016 (Man. Year: 2015) Chassis No: VSKYBAM20Z0120540
Colour: Silver Odometer: 0 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,058.50	1,512.36	4,546.14	75.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,630.00	1,890.00	53.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,578.50	3,142.36	6,436.14	67.19
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	9,578.50	2,500.00	7,078.50	73.90
+ GST 7.00/7.00% (S\$)	670.50	175.00	495.50	73.90
Nett Amount (S\$)	10,249.00	2,675.00	7,574.00	73.90

INSPECTION

Date of Assignment: 26/10/2021
Date Inspected: 26/10/2021 Inspected At: 8 KAKI BUKIT AVENUE 4 #02-13
Estimated Period of Repair: 6.0 days Repairer: SAT MOTORS (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Nov 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE6851X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT DOOR RH	Not Necessary	855.00 F	*- FL
2	1		*REAR BUMPER	Not Necessary	695.80 F	*- FL
3	1		*REAR BUMPER RIGHT REFLECTOR	Not Necessary	112.60 F	*- FL
4	1		*RIGHT REAR BUMPER BRACKET	Not Necessary	65.60 F	*- FL
5	1		*RIGHT REAR TAIL LAMP	Not Necessary	65.60 F	*- FL
6	1		*REAR RIGHT FENDER	Dented	496.00 F	*496.00 FL
7	1		*SET LEFT REAR BUMPER BRACKET	Not Necessary	759.90 F	*- FL
8	1		*REAR RIGHT FENDER RAIL	Cut	356.20 F	*289.40 FL
9	1		*FRT RH DOOR	Buckled	895.00 F	*895.00 FL
10	1		*FRT RIGHT PASSENGER DOOR GLASS	Not Necessary	325.60 F	*- FL
11	1		*REAR RIGHT SLIDING DOOR	Repair	1,105.60 F	*- FL
12	1		*REAR RIGHT FENDER GLASS WINDOW	Not Necessary	325.60 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,058.50	1,680.40
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	168.04
Total Parts (\$)	6,058.50	1,512.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FIX & DISMANTLE AND REMOVE DAMAGED REAR TO FRONT RIGHT AFFECTED DAMAGED PORTION	New	600.00	400.00
2	TO APPLY ANTI RUST COAT AND AFFECTED AREAS (NPA)	New	0.00	0.00
3	TO CHECK WIRING	New	120.00	30.00
4	WELDING AND CUTTING OF AFFECTED PANELS, INLCUDING CHASSIS ALIGNMENT	New	1,000.00	400.00
5	SPRAY PAINTING FOR FRONT RIGHT PORTIONS AFFECTED PARTS	New	1,500.00	800.00
6	REFOCUSING OF THE FRONT HEADLAMP (NPA)	New	0.00	0.00
7	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE	New	120.00	0.00
8	3D WHEEL ALIGNMENT	New	180.00	0.00
9	TO APPLY WATERPROOFING SEALER ON END PANELS (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			3,520.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >