

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21009493/EES3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SLE9455T **Insured Vehicle No :** SLT9263B  
 Date of Loss: 31/08/2021 Nature of Claim: TP Claim No: MFL2021D0003835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE9455T**  
 Make & Model: MASERATI QUATTROPORTE S, 3.0 (A) Engine No: M15746D131796  
 Reg. Date: 08/08/2016 (Man. Year: 2014) Chassis No: ZAMTP56C001131082  
 Colour: Blue Odometer: 118105 km  
 Engine Capacity: 2987 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R19 Rear Tyre Size: 245/45Z R19  
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm  
 Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,413.78	2,971.88	441.90	12.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,535.00	4,150.00	7,385.00	64.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,948.78</b>	<b>7,121.88</b>	<b>7,826.90</b>	<b>52.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,046.41	498.53	547.88	52.36
<b>Nett Amount (S\$)</b>	<b>15,995.19</b>	<b>7,620.41</b>	<b>8,374.78</b>	<b>52.36</b>
<b>+ Loss of Use (4.0 x S\$180.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,347.86</b>		

INSPECTION

Date of Assignment: 09/09/2021  
 Date Inspected: 10/09/2021 Inspected At: Tridente Automobili Pte Ltd (HQ)  
 30 Leng Kee Road #01-02  
 Singapore 159100  
 Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 02 Nov 2021)

**Parts:** 143      MASERATI QUATTROPORTE S 3.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLE9455T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER AND REAR AERODY	Dented	2,280.50 FS	*2,280.50 FS
2	1		*REAR BUMPER RIGHT SIDE MOUNT	Not Necessary	89.70 FS	*- FS
3	1		*REAR BUMPER LEFT SIDE MOUNTI	Not Necessary	89.70 FS	*- FS
4	6		*SCREW	Not Necessary	15.00 FS	*- FS
5	4		*SEAL VG12-04810-511	Necessary	15.20 FS	*15.20 FS
6	1		*REAR LH PARK SENSOR SLEEVE	Necessary	108.25 FS	*108.25 FS
7	1		*REAR LH PARK SENSOR SLEEVE	Necessary	108.25 FS	*108.25 FS
8	1		*REAR RH PARK SENSOR SLEEVE	Necessary	108.25 FS	*108.25 FS
9	1		*REAR RH PARK SENSOR SLEEVE	Necessary	108.25 FS	*108.25 FS
10	4		*SILICON RING	Necessary	79.60 FS	*79.60 FS
11	10		*RIVET	Necessary	65.00 FS	*65.00 FS
12	1		*REAR BUMPER FASTENING CENTER	Not Necessary	172.50 FS	*- FS
13	1		*SUNDRY	Necessary	150.00 FS	*75.00 FS
14	6		*SPECIAL SCREW	Necessary	23.58 FS	*23.58 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **3,413.78**      **2,971.88**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTE	New	5,280.00	1,320.00
2	TO SPRAY PAINT ON REAR 2 OUTER PANEL 1 INNER PANE	New	3,900.00	1,300.00
3	TO CHECK AND CLEAR FAULT AFTER ACCIDENT REPAIR	New	1,200.00	1,200.00
4	TO CHECK ELECTRICAL WIRING SYSTEMFOR PROPER FU	New	660.00	330.00
5	PERFORM WHEEL ALIGNMENT ADJUST AFTER REPAIR	New	495.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>11,535.00</b>	<b>4,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >