

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21009496/AGA3Q2

Date:

11/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : SLJ4863E**Insured Vehicle No :**

GBH6743J

Date of Loss: 07/09/2021

Nature of Claim:

TP

Claim No:

MFL2021D0004081

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLJ4863E**

Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A)

Engine No:

L15B31190666

Reg. Date: 13/12/2016 (Man. Year: 2016)

Chassis No:

JHMGK5850HX200960

Colour: Maroon

Odometer:

270953 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size:

185/55 R16

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,107.88	1,732.00	4,375.88	71.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,310.00	540.00	29.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,957.88	3,042.00	4,915.88	61.77
Approved Total (Overridden) (S\$)		2,400.00		

(S\$)	7,957.88	2,400.00	5,557.88	69.84
+ GST 7.00/7.00% (S\$)	557.05	168.00	389.05	69.84
Nett Amount (S\$)	8,514.93	2,568.00	5,946.93	69.84
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
Nett Liability (S\$)		3,210.00		

INSPECTION

Date of Assignment: 09/09/2021

Date Inspected: 15/09/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Hua Hong Pte Ltd (Sungei Kadut)
 10 Kaki Bukit Avenue 4, #04-63 Premier @ Kaki Bukit
 Singapore 415874

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ4863E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,379.00 FL	*497.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Necessary	75.00 FL	*75.00 FL
4	1		*REAR TAILGATE	Distorted	2,005.00 FL	*755.00 FL
5	1		*REAR TAILGATE LOCK	Damaged	525.00 FL	*157.00 FL
6	1		*REAR TAILGATE CHROME	Cut	686.70 FL	*234.00 FL
7	1		*REAR TAILGATE EMBLEM	Necessary	64.75 FL	*40.00 FL
8	1		*REAR TAILGATE LOGO (JAZZ)	Necessary	68.25 FL	*42.00 FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	420.00 FL	*85.00 FL
10	1		*REAR TAIL LAMP (RH)	Not Necessary	785.10 FL	*- FL
11	1		*REAR END PANEL	Repair	1,054.80 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	227.50 FL	*- FL
13	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
14	1		*REAR REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,576.10	2,115.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,468.22	383.00
Total Parts (\$\$)	6,107.88	1,732.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT & WELD REAR END PANEL ,CHARGE REAR BUMPER ,REAR TAILGATE ,KNOCKING ALL AREA AFFECTED BY ACCIDENT	New	800.00	500.00
2	TO PERFORM WIRE CHECKING	New	50.00	30.00
3	TO TRANSFER REAR TAILGATE MECHANISM TO NEW TAILGATE	New	80.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	TO SPRAY REAR END PANEL ,REAR BUMPER ,REAR TAILGATE AND ALL AFFECTED AREA	New	800.00	600.00
Gross Labour Cost (S\$)			1,850.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >