

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21009499/UUF3E2

Date: 21/10/2021

REFERENCE

Insured/Claimant:	JIAXING AIRCON PTE LTD	Policy No:	7210081588	
Date of Loss:	04/09/2021	Nature of Claim:	OD	Claim No: 3791577600SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9421D		
Make & Model:	TOYOTA HIACE, 2.0 (M)	Engine No:	1KD2639645
Reg. Date:	17/04/2017 (Man. Year: 2016)	Chassis No:	KDH2015023948
Colour:	White	Odometer:	119647 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,847.56	3,283.45	5,564.11	62.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,520.00	960.00	38.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,327.56	4,803.45	6,524.11	57.60
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,727.56	4,203.45	6,524.11	60.82
+ GST 7.00/7.00% (S\$)	750.93	294.24	456.69	60.82
Nett Amount (S\$)	11,478.49	4,497.69	6,980.80	60.82

INSPECTION

Date of Assignment:	09/09/2021	
Date Inspected:	21/09/2021 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET (WCP)	Repair	260.00 F	*- F
2	1	*FRONT BONNET LOGO (WCP)	Not Necessary	35.00 F	*- F
3	1	*FRONT BONNET LOCK (WCP)	Not Necessary	65.00 F	*- F
4	1	*FRONT BUMPER (WCP)	Distorted	220.00 F	*220.00 F
5	2	*FRONT BUMPER TOW COVER - L/R (WCP)	Missing / Torn	36.00 F	*36.00 F
6	1	*FRONT BUMPER SIDE COVER - LH (WCP)	Twisted	48.00 F	*48.00 F
7	1	*FRONT BUMPER CENTRE GRILLE (WCP)	Torn	89.00 F	*89.00 F
8	1	*FRONT BUMPER TOP BEAM (WCP)	Repair	155.00 F	*- F
9	1	*FRONT BUMPER REINFORCEMENT (WCP)	Dented	285.00 F	*285.00 F
10	1	*FRONT BUMPER BRACKETS - L/R (WCP)	N/S Bent	220.00 F	*110.00 F
11	1	*FRONT BUMPER SIDE RETAINERS - L/R (WCP)	N/S Cracked	321.80 F	*95.00 F
12	1	*SET FRONT BUMPER CLIPS (WCP)	Necessary	35.00 F	*35.00 F
13	1	*FRONT CORNER PANEL - LH (WCP)	Repair	165.00 F	*- F
14	1	*FRONT DOOR - LH (WCP)	Dented / Bent	850.00 F	*850.00 F
15	1	*FRONT DOOR W/STRIP (WCP)	Not Necessary	120.00 F	*- F
16	1	*FRONT DOOR SEAL (WCP)	Necessary	85.00 F	*85.00 F
17	1	*FRONT DOOR GLASS OUTER MOULDING (WCP)	Not Necessary	122.00 F	*- F
18	1	*FRONT DOOR GLASS RUN CHANNEL (WCP)	Not Necessary	160.00 F	*- F
19	1	*FRONT DOOR CHECKER (WCP)	Not Necessary	85.00 F	*- F
20	1	*FRONT DOOR PILLAR - LH (WCP)	Repair	450.00 F	*- F
21	1	*FRONT GRILLE - TOP (WCP)	Cracked	180.00 F	*180.00 F
22	1	*FRONT GRILLE - LOWER (WCP)	Cracked	160.00 F	*160.00 F
23	1	*FRONT GRILLE BASE (WCP)	Cracked	195.00 F	*195.00 F
24	1	*FRONT HEADLAMPS - L/R (WCP)	N/S Broken / O/S Not Necessary	570.00 F	*285.00 F
25	2	*FRONT HEADLAMP CLIPS - LOWER (WCP)	Not Necessary	36.00 F	*- F
26	2	*FRONT HEADLAMP CLIPS - L/R (WCP)	Not Necessary	36.00 F	*- F
27	1	*FRONT SUPPORT PANEL (WCP)	Repair	260.00 F	*- F
28	1	*AIR CON CONDENSER (WCP)	Not Necessary	480.00 F	*- F
29	1	*RADIATOR ASSY (WCP)	Not Necessary	750.00 F	*- F
30	1	*RADIATOR SPARE TANK (WCP)	Not Necessary	185.00 F	*- F
31	1	*WIPER TANK (WCP)	Not Necessary	185.00 F	*- F
32	1	*STEP GARNISH - LH (WCP)	Torn	130.00 F	*130.00 F
33	1	*SET FRONT NO. PLATE WITH HOLDER	Cracked	45.00 FS	*40.00 FS
34	1	*BOT AIR CON OIL	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*BOT RADIATOR COOLANT	Not Necessary	65.00 FS	*- FS
36	1		*SET ROC STICKER N/S	Necessary	45.00 FS	*20.00 FS
37	2		*FRONT HEADLAMP LOWER BRACKETS - L/R (WCP)	No such part	220.00 F	*- F
F=Franchise part. S=SpcNett.						
					Sub Total (\$)	7,408.80 2,863.00
					+ Margin on L,N Items 20.00/15.00% (\$)	1,438.76 420.45
					Total Parts (\$)	8,847.56 3,283.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	150.00	0.00
3	TO RESPRAY PAINTING AND ETC	New	1,080.00	700.00
4	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,480.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >