

Insured Policy No. Sum Insured Fyress

Our Reference Date

· KAAS/TA/4866/6387/TP/11 17 : 24 January 2018

To: Puvaneswaran Pillai Arutselvan

c/o 10 Kaki Bukit Road 2

#03-37/38

First East Centre Singapore 417868

## VEHICLE APPRAISAL REPORT

Name of Workshop

: Our Bro's Workshop (S) Pte Ltd

Place of inspection

: 10 kaki Bukit Road 2 #03-37/38, First East Centre, Singapore 417868

Date of Assignment Date of Accident Date of Inspection

· 17 November 2017 : 16 November 2017 : 17 November 2017

### PARTICULARS OF INSPECTED VEHICLE

Registration No. Make/Model

: JSG 6387

: KTM

RC200

Engine No. Chassis Frame No. : HIDDEN FROM VIEW : PNGJYC40XFK027301

Year of Manufacture/Reg

Colour

: Orange

Class/Type

: 2017 : Motorcycle

Odometer Reading

: 5.948 KM

### CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition Paintwork Footbrakes

Steering

· Good : Good

: Serviceable

: Serviceable

Undercarriage (Front) Undercarriage (Rear)

: Serviceable : Serviceable

Market Value

Scrap Value (PARF/OMV) · -

#### CONDITION OF TYRES ON VEHICLE

Make/Size

MRF REVZ - FC 110 / 70 R17 MRF REVZ - FC 150 / 60 R17 MRF REVZ - FC 110 / 70 R17 Thread Balance 8mm 8mm 8mm 8mm

Rear Left Front Right Rear Right

Front Left

MRF REVZ - FC 150 / 60 R17

\*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

Our Reference Vehicle Number : KAAS/TA/4866/6387/TP/11.17 : JSG 6387

# ASSESSMENT SUMMARY

Damages sustained were consistent with the accident report.







(Please refer to the parts list and photographs as attached for more information)

## ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs

Our Bro's Workshop (S) Pte Ltd

10.970.00 .

We have adjusted the cost to \$

9,357.50 and the repairer has agreed to undertake the repairs at a

Contract Lump Sum of \$ 7,500.00 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of

working days.

29 photographs were taken at the time of static inspection.

only 29 phro. from. KAAS

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No.

we thank you for engaging our services.

4866

for our services rendered and

Kelvin Automotive Appraising Services

Licensed Automotive Appraiser

Nitec in Automotive Technology

Dip MS

MSAAA

Gus gian Us 2050 3 Ly

Submit U/4 @ 4400


NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

Our Reference Vehicle Number : KAAS/TA/4866/6387/TP/11.17

: JSG 6387

# APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/	Repairer's	Revised
			Conditions	Estimate	Amount
Partie (S)		LIST ITEMS:-	Device and an artist and an artist and an artist and artist artist artist artist and artist		
1	1 nois	Front fork const. C. 4.	Buckled	\$ 1,400.00	\$ 1,400.00
2	1 pair	Front fork assy SVC		\$ 325.00	\$ 325.00
3	1 pc	the state of the s	Buckled	\$ 395.00	\$ 395.00
4	1 pc	Front under bracket AA (Cantisee Day &	Buckled	\$ 315.00	\$ 315.0
5	1 pc	Front upper clamp AA (Cantsee Date)	Broken	\$ 255.00	\$ 255.00
6	130	Light Hillochica 12160	Broken	\$ 900.00	\$ 900.00
7	1 pc	Headlamp assy 500 Head fairing 300	Broken	\$ 650.00	\$ 650.00
8	1 pc	Head fairing 300	Not Working	\$ 565.00	\$ 565.00
9	1 pc		Buckled	\$ 78.00	\$ 78.00
10	1 pair	Handlebar grip Cun	Damaged	56.00	\$ 56.00
11	1 pair 1 pair		Damaged	\$ 40.00	\$ 40.00
12	'			\$ 37.00	\$ 37.00
13	1 pc	The state of the s	Buckled	\$ 39.00	\$ 39.00
14	1 pc		Broken	\$ 320.00	\$ 320.00
	1 pair	Wing mirror w/ arm Gro	Deformed	\$ 210.00	\$ 210.00
15 16	1 pc	Front (side) fairing @S\$450.00 CNa/Cu1	Cracked	\$ 900.00	\$ 900.00
17	2 pcs	Front ( under ) fairing @\$\$430.00 C/V	Broken	\$ 440.00	\$ 440.00
18	1 pair		Damaged	\$ 450.00	Repair
	1 set		Broken	\$ 80.00	\$ 80.00
19 20	1 pair	170	Buckled	\$ 270.00	\$ 270.00
20	1 pair	Pillion rider foot rest support bracket	Duckied	210.00	210.00
				\$ 7,725.00	\$ 7,275.00
		Less 10%			\$ 727.50
				\$ 7,725.00	\$ 6,547.50
		SPECIAL NETT ITEMS:-			
21	1 pc	Front wheel rim	Distorted	\$ 650.00	\$ 500 650.00
22	1 pc	Front tyre @ 50% depreciation Sca 17200	1) / Scratched	\$ 360.00	\$ 180.00
23	1 set	Decorative stickers nuc	Necessary	\$ 350.00	\$ 350.00
24	1 pc	Front no. plate sticker	Necessary	\$ 35.00	\$ 20.00
				\$ 1,395.00	\$ 1,200.00
				A TO THE REAL PROPERTY.	
				S S S	Services
			Sub - Total	\$ 9,120.00	\$ 7,747.50



Our Reference Vehicle Number : KAAS/TA/4866/6387/TP/11.17

: JSG 6387

# APPRAISEMENT SCHEDULE

Conditions  B/F  LABOUR & OTHER CHARGES:-  To dismantle and replace damaged parts  To check wiring and rewire	Estimate   Amount   \$ 9,120.00 \$ 7,747.50
LABOUR & OTHER CHARGES:- To dismantle and replace damaged parts To check wiring and rewire	
To realign front fork To do body frame alignment Towing charges To anti-rust To putty and spray-paint of affected areas	\$ 800.00 \$ \$ 0.700.00 \$ \$ 100.00 \$ \$ 200.00 \$ \$ 60 180.00 \$ \$ 150.00 \$ 120.00 \$ 100.00 \$ 120.00 \$ 1,850.00 \$ 1