



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSG 6387

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	PAIR FRONT FORK ASSY	SERVICEABLE	1,400.00	-
1	FRONT BRACE DISC (NO PHOTO SHOW DAMAGE)	NOT NECESSARY	325.00	-
1	FRONT UNDER BRACKET (CAN'T SEE DAMAGE)	NOT NECESSARY	395.00	-
1	FRONT UPPER CLAMP (CAN'T SEE DAMAGE)	NOT NECESSARY	315.00	-
1	FRONT WINDSHIELD	BROKEN	255.00	255.00
1	HEADLAMP ASSY	BROKEN	900.00	900.00
1	HEAD FAIRING	BROKEN	650.00	650.00
1	INSTRUMENTAL PANEL	CRACKED	565.00	565.00
1	PAIR HANDLEBAR	BENT	78.00	78.00
1	PAIR HANDLEBAR GRIP	CUT	56.00	56.00
1	PAIR HANDLEBAR BALANCER	NOT FITTED	40.00	-
1	LH CLUTCH CONTROL LEVER (NO PHOTO SHOW DAMAGE)	NOT NECESSARY	37.00	-
1	RH BRAKE CONTROL LEVER	BENT	39.00	39.00
1	PAIR WING MIRROR W/ARM	BROKEN	320.00	320.00
1	FRONT FENDER	CUT	210.00	210.00
2	FRONT (SIDE) FAIRING @\$450.00	CRACKED / CUT	900.00	900.00
1	PAIR FRONT (UNDER) FAIRING @\$220.00	CRACKED	440.00	440.00
1	SET REAR FAIRING	TO REPAIR SEE LABOUR	450.00	-
1	PAIR PILLION RIDER FOOT REST	BROKEN	80.00	80.00
1	PAIR PILLION RIDER FOOT REST SUPPORT BRACKET	BUCKLED	270.00	270.00
	LESS 10% DISCOUNT		-	-476.30
			7,725.00	4,286.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WHEEL RIM (SN)	CUT	650.00	500.00
1	FRONT TYRE (\$200.00) (50%) (SN)	SCRATCHED	360.00	100.00
1	SET DECORATIVE STICKERS (SN)	NECESSARY	350.00	200.00
1	FRONT NO. PLATE STICKER (SN)	NECESSARY	35.00	15.00
			1,395.00	815.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISMANTLE AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF 1 SET REAR FAIRING.		800.00	300.00
	TO CHECK WIRING AND REWIRE.	NOT NECESSARY	100.00	-
	TO REALIGN FRONT FORK.		200.00	60.00
	TO DO FRAME ALIGNMENT.	NOT NECESSARY	180.00	-
	TOWING CHARGE.		100.00	40.00
	TO ANTI-RUST.	NOT NECESSARY	120.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.	NOT NECESSARY	350.00	-
			1,850.00	400.00
	<b>GRAND TOTAL</b>		<b>10,970.00</b>	<b>5,501.70</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,400.00</b>

Report Ref No. CS3/CTI17022248/Uqce2-1

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.