

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009505/R1VCN2**Date:** 17/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00143252100
Claimant Vehicle No :	SLR4129A	Insured Vehicle No :	SMU6993E
Date of Loss:	06/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205038/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4129A	Engine No:	LEB4266414
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71046142
Reg. Date:	15/08/2017 (Man. Year: 2016)	Odometer:	399037 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,788.00	960.00	1,828.00	65.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	650.00	950.00	59.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,388.00	1,610.00	2,778.00	63.31
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	4,388.00	1,300.00	3,088.00	70.37
+ GST 7.00/7.00% (\$\$)	307.16	91.00	216.16	70.37
Nett Amount (\$\$)	4,695.16	1,391.00	3,304.16	70.37

INSPECTION

Date of Assignment:	10/09/2021	
Date Inspected:	13/09/2021	Inspected At: Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-35/36 Carros Centre Singapore 737569
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Nov 2021)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR4129A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/R DOOR	Buckled	1,575.00 FL	*1,200.00 FL
2	1		*R/R DOOR WINDOW REGULATOR	Serviceable	480.00 FL	*- FL
3	1		*R/R DOOR WINDOW MOTOR ASSY	Serviceable	680.00 FL	*- FL
4	1		*RH SIDE SKIRT	Repair	750.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,485.00	1,200.00
- List Item Discount on L Items 20.00/20.00% (\$)	697.00	240.00
Total Parts (\$)	2,788.00	960.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING R/R DOOR,R/R FENDER AND RH SIDE SKIRT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	800.00	350.00
2	TO RESPRAY REAR BUMPER,R/R DOOR,R/R FENDER,RH SIDE SKIRT	New	800.00	300.00
Gross Labour Cost (\$)			1,600.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >