

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009506/BVCN2**Date:** 22/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00006262101
Claimant Vehicle No :	SLW9669Z	Insured Vehicle No :	SME9018K
Date of Loss:	05/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205046/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9669Z	Engine No:	65192133925448
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Chassis No:	WDC2539092F218408
Reg. Date:	08/12/2017 (Man. Year: 2017)	Odometer:	39927 km
Colour:	Blue		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55ZR19	Rear Tyre Size:	235/55ZR19
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,294.60	8,271.65	10,022.95	54.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,770.00	1,660.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,724.60	10,041.65	11,682.95	53.78
Approved Total (Overridden) (\$\$)		8,050.00		
(\$\$)	21,724.60	8,050.00	13,674.60	62.95
+ GST 7.00/7.00% (\$\$)	1,520.72	563.50	957.22	62.95
Nett Amount (\$\$)	23,245.32	8,613.50	14,631.82	62.95

INSPECTION

Date of Assignment:	09/09/2021	
Date Inspected:	10/09/2021 Inspected At:	Bifront Auto Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW9669Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	3,090.00 FL	*2,025.00 FL
2	1	*TAILGATE WINDSCREEN GLASS WITH RUBBER MOULDING	Not Damaged	1,183.00 FL	*- FL
3	1	*TAILGATE GLC 25D EMBLEM	Necessary	103.00 FL	*98.00 FL
4	1	*TAILGATE CENTRE EMBLEM	Necessary	172.00 FL	*101.00 FL
5	1	*TAILGATE 4 MATIC EMBLEM	Necessary	103.00 FL	*98.00 FL
6	1	*TAILGATE LOCK	Jammed	318.00 FL	*318.00 FL
7	1	*TAILGATE INNER TRIM BOARD	Broken	558.00 FL	*558.00 FL
8	1	*TAILGATE RH LAMP ASSY	Not Damaged	759.00 FL	*- FL
9	1	*TAILGATE LH LAMP ASSY	Not Damaged	759.00 FL	*- FL
10	1	*REAR BUMPER (UPPER)	Broken	1,365.00 FL	*940.00 FL
11	1	*REAR BUMPER RH REFLECTOR	Cut	38.00 FL	*31.00 FL
12	1	*REAR BUMPER LH REFLECTOR	Cut	38.00 FL	*31.00 FL
13	1	*REAR BUMPER REINFORCEMENT	Dented	817.00 FL	*764.50 FL
14	1	*REAR BUMPER INNER SPONGE	No such part	195.00 FL	*- FL
15	1	*REAR BUMPER (CENTRE)	Broken	794.00 FL	*305.00 FL
16	1	*REAR BUMPER TOWING CENTRE	Not Damaged	69.00 FL	*- FL
17	1	*REAR BUMPER LOWER DIFFUSER	Broken	490.00 FL	*490.00 FL
18	1	*REAR BUMPER RH SIDE REVERSE SENSOR	Not Damaged	194.00 FL	*- FL
19	1	*REAR BUMPER RH CENTRE REVERSE SENSOR	Short Circuit	194.00 FL	*170.00 FL
20	1	*REAR BUMPER LH CENTRE REVERSE SENSOR	Short Circuit	194.00 FL	*170.00 FL
21	1	*REAR BUMPER LH SIDE REVERSE SENSOR	Not Damaged	194.00 FL	*- FL
22	4	*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	130.00 FL	*130.00 FL
23	4	*REAR BUMPER REVERSE SENSOR O-RINGS	Necessary	22.00 FL	*22.00 FL
24	1	*REAR BUMPER RH SIDE RETAINER	Necessary	112.00 FL	*105.00 FL
25	1	*REAR BUMPER LH SIDE RETAINER	Necessary	112.00 FL	*105.00 FL
26	1	*REAR BUMPER RH LOWER SIDE BRACKET	Broken	68.00 FL	*68.00 FL
27	1	*REAR BUMPER LH LOWER SIDE BRACKET	Broken	68.00 FL	*68.00 FL
28	1	*REAR BUMPER RH EXHAUST CHROME MOULDING	Not Damaged	415.00 FL	*- FL
29	1	*REAR BUMPER LH EXHAUST CHROME MOULDING	Not Damaged	415.00 FL	*- FL
30	1	*RH TAILLAMP	Broken	785.00 FL	*785.00 FL
31	1	*RH TAILLAMP LOWER BRACKET	Broken	154.00 FL	*90.00 FL
32	1	*LH TAILLAMP	Broken	785.00 FL	*785.00 FL
33	1	*LH TAILLAMP LOWER BRACKET	Broken	154.00 FL	*90.00 FL
34	1	*REAR RH FENDER WHEEL ARCH MOULDING	Not Damaged	268.00 FL	*- FL
35	1	*REAR LH FENDER WHEEL ARCH MOULDING	Not Damaged	268.00 FL	*- FL
36	1	*END PANEL	Not Necessary	1,875.00 FL	*- FL
37	1	*END PANEL INNER GARNISH	Broken	420.00 FL	*367.00 FL
38	1	*EXHAUST SILENCER	Not Damaged	1,637.00 FL	*- FL
39	1	*EXHAUST SILENCER HEAT SHIELD	Dented	251.00 FL	*126.00 FL
40	1	*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
41	1	*TAILGATE WINDSCREEN GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
42	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
43	1	*REAR BUMPER LOWER DIFFUSER RED STRIP STICKER	Necessary	70.00 FS	*20.00 FS
44	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
45	1	*SET REAR RH FENDER WHEEL ARCH MOULDING CLIPS	Not Necessary	70.00 FS	*- FS
46	1	*SET REAR LH FENDER WHEEL ARCH MOULDING CLIPS	Not Necessary	70.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER CENTRE BRACKET	Broken	228.00 FL	*228.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	20,274.00
					9,178.50	
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,979.40
						906.85
					Total Parts (S\$)	18,294.60
						8,271.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK ALL WIRING AND ALL LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	40.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS	New	220.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	180.00	80.00
7	REMOVE,REINSTALL AND ADJUST TAILGATE REVERSE CAMERA	New	100.00	0.00
8	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	250.00	120.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS AND WIRE HARNESS	New	120.00	60.00
10	REMOVE AND REPLACE EXHAUST SILENCER AND HEAT SHIELD	New	150.00	30.00
11	RESET AND DIAGNOSE FAULT CODE FROM CONTROL UNIT	New	250.00	120.00
Gross Labour Cost (\$\$)			3,430.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >