

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009507/APS3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210081588
Claimant Vehicle No :	SKW236K	Insured Vehicle No :	GBF9421D
Date of Loss:	04/09/2021	Nature of Claim:	TP
		Claim No:	3791577600SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW236K	Engine No:	A1920976N20B20A
Make & Model:	BMW 428i, 2.0 Gran Coupe (F36) (A)	Chassis No:	WBA4A52030GA69376
Reg. Date:	09/02/2015 (Man. Year: 2014)	Odometer:	134907 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30 R19	Rear Tyre Size:	275/30 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,209.93	16,758.69	21,451.24	56.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,160.00	4,000.00	1,160.00	22.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,369.93	20,758.69	22,611.24	52.14
Approved Total (Overridden) (S\$)		16,600.00		
(S\$)	43,369.93	16,600.00	26,769.93	61.72
+ GST 7.00/7.00% (S\$)	3,035.90	1,162.00	1,873.90	61.72
Nett Amount (S\$)	46,405.83	17,762.00	28,643.83	61.72
+ Car Rental (12.0 x S\$170.00/day) (S\$)		2,040.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		19,809.45		
Global Sum Settlement (S\$)		19,800.00		

INSPECTION

Date of Assignment:	08/09/2021	
Date Inspected:	08/09/2021	Inspected At: New Zen Werkz Pte Ltd (HQ) Blk 3 kaki Bukit road 1 #03-04 Eunost Technolink Singapore 415935
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BATTERY	Deformed	220.00 F	*220.00 FL
2	1		*FRONT DOOR -RH	Dented	1,852.20 F	*1,852.20 FL
3	1		*FRONT DOOR TOP HINGE	Not Necessary	185.10 F	*- FL
4	1		*FRONT DOOR LOWER HINGE	Not Necessary	185.30 F	*- FL
5	1		*FRONT DOOR INNER GEAR	Not Necessary	588.00 F	*- FL
6	1		*FRONT DOOR INNER MOTOR	Not Necessary	625.00 F	*- FL
7	1		*FRONT DOOR INNER LOCK	Not Necessary	561.80 F	*- FL
8	1		*FRONT DOOR SIDE MIRROR -RH	Damaged	981.40 F	*981.40 FL
9	1		*FRONT DOOR TOP MOULDING	Not Necessary	221.20 F	*- FL
10	1		*FRONT DOOR INNER TRIM BOARD	Not Necessary	1,450.10 F	*- FL
11	1		*FRONT DOOR INNER RUBBER	Necessary	182.25 F	*182.25 FL
12	1		*FRONT DOOR INNER SPONGE	Not Necessary	125.00 F	*- FL
13	1		*FRONT DOOR PILLAR	Repair	852.60 F	*- FL
14	1		*FRONT DOOR HANDLE -RH	Repair	188.20 F	*- FL
15	1		*REAR R/H DOOR	Dented	1,852.20 F	*1,852.20 FL
16	2		*REAR R/H DOOR HINGES	Not Necessary	370.60 F	*- FL
17	1		*REAR DOOR TOP MOULDING	Not Necessary	221.20 F	*- FL
18	1		*REAR R/H DOOR INNER LOCK	Jammed	570.00 F	*570.00 FL
19	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	1,358.00 F	*- FL
20	1		*REAR R/H DOOR GLASS GEAR	Damaged	458.00 F	*458.00 FL
21	1		*REAR RH DOOR POWER WINDOW	Not Necessary	568.00 F	*- FL
22	1		*REAR R/H DOOR GEAR MOTOR	Not Necessary	552.00 F	*- FL
23	1		*REAR R/H LOWER SKIRT	Repair	588.20 F	*- FL
24	15		*REAR R/H LOWER SKIRT CLIPS	Not Necessary	52.50 F	*- FL
25	1		*REAR R/H FENDER	Distorted	1,685.00 F	*1,685.00 FL
26	1		*REAR SIDE TOP FENDER -RH	Not Necessary	854.00 F	*- FL
27	1		*REAR SIDE LOWER FENDER-RH	Dented	755.00 F	*325.00 FL
28	1		*REAR FENDER INNER TRIM BOARD -RH	Not Necessary	785.00 F	*- FL
29	1		*REAR AIR DUCT -RH	Cracked	155.00 F	*155.00 FL
30	1		*REAR FUSE BOX	Cracked	325.00 F	*325.00 FL
31	1		*REAR SPORT RIM-RH	Cut	1,100.00 F	*1,100.00 FL
32	1		*REAR R/H SHOCK ABSORBER	Not Necessary	581.20 F	*- FL
33	1		*REAR R/H TIRE	Cut	650.00 FS	*300.00 FS
34	1		*REAR R/H LOWER ARM	Bent	523.20 F	*523.20 FL
35	1		*REAR R/H KNUCKLE ARM	Damaged	1,295.00 F	*1,295.00 FL
36	1		*REAR R/H KNUCKLE ARM BEARING	Damaged	460.00 F	*460.00 FL
37	1		*BOOT LID	Not Necessary	1,952.10 F	*- FL
38	2		*REAR BOOT LID HINGES	Not Necessary	240.00 F	*- FL
39	1		*REAR BOOT LID EMBLE LOGO	Not Necessary	75.00 F	*- FL
40	2		*REAR BOOT LID EMBLE LOGO CLIPS	Not Necessary	13.00 F	*- FL
41	1		*REAR BOOT LID 428I LOGO	Not Necessary	60.00 F	*- FL
42	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	70.00 F	*- FL
43	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
44	1		*REAR BOOT LID INNER LOCK	Not Necessary	558.20 F	*- FL
45	1		*REAR BOOT LID INNER RUBBER	Not Necessary	265.00 F	*- FL
46	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	625.00 F	*- FL
47	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	55.00 F	*- FL
48	1		*BOOT LID NUMBER PLATE GARNISH	Not Necessary	219.50 F	*- FL
49	1		*BOOT LID SIDE REFLECTOR -RH	Not Necessary	255.00 F	*- FL
50	1		*REAR TAIL LAMP -RH	Smashed	752.10 F	*752.10 FL
51	4		*REAR TAIL LAMP CLIPS	Necessary	22.00 F	*22.00 FL
52	1		*REAR BUMPER	Distorted	1,652.20 F	*1,652.20 FL
53	1		*REAR BUMPER SIDE BRACKET	O/S Damaged	310.00 F	*155.00 FL
54	1		*REAR BUMPER REVERSE SENSOR (4 PCS)	Damaged (1 PCS ONLY)	1,198.00 F	*299.50 FL
55	1		*REAR BUMPER TOWING COVER	Not Necessary	88.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR BUMPER SIDE REFLECTOR -RH	Cracked	95.00 F	*95.00 FL
57	1		*REAR BUMPER REINFORCEMENT	Not Necessary	570.00 F	*- FL
58	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	260.00 F	*- FL
59	1		*REAR BUMPER INNER SPONGE	Not Necessary	285.00 F	*- FL
60	1		*REAR BUMPER LOWER CENTER COVER	Not Necessary	285.00 F	*- FL
61	8		*REAR BUMPER LOWER CENTER COVER CLIPS	Not Necessary	52.00 F	*- FL
62	1		*REAR BUMPER LOWER COVER	Not Necessary	325.00 F	*- FL
63	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*65.00 FL
64	1		*REAR BUMPER CENTER LOWER GARNISH	Not Necessary	185.00 F	*- FL
65	1		*REAR END PANEL	Dented	921.38 F	*921.38 FL
66	1		*REAR END PANEL TOP GARNISH	Not Necessary	203.20 F	*- FL
67	1		*REAR EXHAUST CHROME PIPE	Not Necessary	185.00 F	*- FL
68	1		*REAR RH CONTROL ARM	Bent	294.00 F	*294.00 FL
69	1		*REAR RH STAY ARM	Bent	251.00 F	*251.00 FL
70	1		*REAR RH LATORAL LINK (FRONT)	Bent	214.00 F	*214.00 FL
71	1		*REAR RH LATORAL LINK (REAR)	Bent	281.00 F	*281.00 FL
72	1		*REAR RH FENDER INNER SHIELD	Torn	236.00 F	*236.00 FL
73	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*30.00 FL
74	1		*FUEL LID	Damaged	102.00 F	*102.00 FL
75	1		*FUEL LID LOCK	Jammed	87.00 F	*87.00 FL
76	1		*FUEL LID INNER TRIM	Deformed	159.00 F	*159.00 FL
77	1		*TAILLAMP PANEL RH	Distorted	298.00 F	*298.00 FL
78	1		*REAR WINDSCREEN MOULDING	Necessary	204.00 F	*204.00 FL
79	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 F	*60.00 FL
80	1		*REAR RH QUARTER GLASS MOULDING	Necessary	85.00 F	*85.00 FL
81	1		*REAR RH QUARTER GLASS SEALANT	Necessary	40.00 F	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,209.93	18,587.43
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,828.74
Total Parts (\$\$)	38,209.93	16,758.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	150.00	80.00
2	TUFF KOTE	New	150.00	80.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	GUM	New	50.00	50.00
5	TO CHECK WIRING SYSTEM	New	60.00	30.00
6	TO REMOVE AND REFIX RH REAR FENDER GLASS	New	150.00	60.00
7	TO REMOVE & REFIX DOOR HANDLE ,GLASS ,GEAR MECHANISM ,MOTOR ,CHECK WIRING & ETC	New	180.00	160.00
8	WHEEL ALIGNMENT (COMPUTER)	New	150.00	80.00
9	TO TOW VEHICLE FROM TRAFFIC POLICE TO WORKSHOP	New	120.00	120.00
10	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	250.00	220.00
11	TO REMOVE & INSTALL RH FRONT & REAR DOOR	New	280.00	0.00
12	TO PANEL BEATING	New	2,000.00	1,600.00
13	SPRAY PAINTING	New	1,500.00	1,400.00
Gross Labour Cost (\$)			5,160.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >