

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21009508/APA3Q2**Date:** 12/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900021674
<b>Claimant Vehicle No :</b>	SMN396E	<b>Insured Vehicle No :</b>	SBD24L
Date of Loss:	06/09/2021	Nature of Claim:	TP
		Claim No:	9390909472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMN396E</b>	Engine No:	LEB1451024
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP51341972
Reg. Date:	23/07/2019 (Man. Year: 2018)	Odometer:	72318 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	464.08	434.08	30.00	6.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	450.00	680.00	60.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,594.08</b>	<b>884.08</b>	<b>710.00</b>	<b>44.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	111.59	61.89	49.70	44.54
<b>Nett Amount (S\$)</b>	<b>1,705.67</b>	<b>945.97</b>	<b>759.70</b>	<b>44.54</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,147.97</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,140.00</b>		

INSPECTION

Date of Assignment:	09/09/2021	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	09/09/2021 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	2.0 days	Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



**SPECIAL REMARKS**

(FOR MANDATE ONLY)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	505.10 FL	*505.10 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					565.10	535.10
- List Item Discount on L Items 20.00/20.00% (\$\$)					101.02	101.02
Total Parts (\$\$)					464.08	434.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	(REAR) TO SPRAY PAINTING	New	600.00	200.00
2	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	450.00	200.00
3	TO REMOVE & REFIX REVERSE SENSOR	New	80.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,130.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >