

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21009512/Bvce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER 07/01/2022 Date: SINGAPORE 068811 ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 8005Z SLF 1979X Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03HGX Excess (\$) 0.00 **CHAN KIAN CHUAN Assign From Assign Date** 10/09/2021 **Vehicle Particulars & Condition** 2. HONDA VEZEL c.c 1496 Make & Model HIDDEN 2016 Engine No. Year of Reg. RU11113508 **BLACK** Chassis No. Colour 212744 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/60 R16 DUNLOP 5 mm DUNLOP L/H Front Tyre 215/60 R16 5 mm 215/60 R16 DUNLOP R/H Rear Tyre 5 mm **DUNLOP** L/H Rear Tyre 215/60 R16 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. 5. **General Information** 04/09/2021 13/09/2021 ( 01:23 PM ) **Accident Date** Inspect Date / Time JP CONCEPTZ PTE LTD Survey held at 160 SIN MING DRIVE #07-11 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM21009512/Bvce2

**Estimate Days of Repair** 

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

**LIM TEOW GUAN** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days