

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009515/KUF3N2**Date:** 22/09/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001804139

Claimant Vehicle No : GBJ941H**Insured Vehicle No :** YP3847Z

Date of Loss: 09/09/2021

Nature of Claim: TP Claim No: 262412

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ941H**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2832160

Reg. Date: 02/01/2019 (Man. Year: 2018)

Chassis No: JTFHT02P300246424

Colour: Silver

Odometer: 83971 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15X8

Rear Tyre Size: 195R15X8

Front Left Side: APLUS 9 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: APLUS 9 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,980.15	922.30	1,057.85	53.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	170.00	230.00	57.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,380.15	1,092.30	1,287.85	54.11
Approved Total (Overridden) (S\$)		850.00		
(S\$)	2,380.15	850.00	1,530.15	64.29
+ GST 7.00/7.00% (S\$)	166.61	59.50	107.11	64.29
Nett Amount (S\$)	2,546.76	909.50	1,637.26	64.29

INSPECTION

Date of Assignment: 10/09/2021

Date Inspected: 10/09/2021 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2021)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ941H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,340.00 FL	*1,115.20 FL
2	1		*REAR TAILGATE WIPER MOTOR	Serviceable	980.10 FL	*- FL
3	1		*REAR TAILGATE WIPER ARM	Serviceable	178.90 FL	*- FL
4	1		*REAR TAILGATE WIPER BLADE	Cut/Distorted	61.20 FL	*61.20 FL
5	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,620.20	1,216.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	640.05	294.10
Total Parts (\$\$)	1,980.15	922.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00	120.00
2	TO CHECK & REARRANGE WIRING	New	50.00	0.00
3	TO REMOVE,REPLACE WIPER COMPONENTS	New	200.00	50.00
Gross Labour Cost (\$\$)			400.00	170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >