

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG21009516/AVF3N2**Date:** 26/10/2021REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800114813   |
| <b>Claimant Vehicle No :</b> | SMA8060P                             | <b>Insured Vehicle No :</b> | GBG7497T     |
| Date of Loss:                | 09/09/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3369240587SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMA8060P</b>                   | Engine No:  | F16D34774101      |
| Make & Model:               | CHEVROLET CRUZE, 1.6 2WD (A)      | Chassis No: | KL1JA6961AK549258 |
| Reg. Date:                  | 28/10/2009 (Man. Year: 2009)      | Odometer:   | 197956 km         |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/45R17        | Rear Tyre Size:  | 225/45R17        |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 30,389.30         | 15,554.00         | 14,835.30         | 48.82         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 6,600.00          | 3,790.00          | 2,810.00          | 42.58         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>36,989.30</b>  | <b>19,344.00</b>  | <b>17,645.30</b>  | <b>47.70</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>12,000.00</b>  |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>36,989.30</b>  | <b>12,000.00</b>  | <b>24,989.30</b>  | <b>67.56</b>  |

INSPECTION

|                             |                          |                                                |
|-----------------------------|--------------------------|------------------------------------------------|
| Date of Assignment:         | 10/09/2021               | MCS GARAGE (HQ)                                |
| Date Inspected:             | 10/09/2021 Inspected At: | 10 KAKI BUKIT ROAD 2, #03-25 FIRST EAST CENTRE |
| Estimated Period of Repair: | 14.0 days                | Singapore 417868                               |

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition             | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|-----------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BONNET                      | Dented                | 1,362.00 FL | *1,362.00 FL |
| 2   | 1   |          | *FRONT BONNET SEAL-CTR             | Not Necessary         | 58.00 FL    | *- FL        |
| 3   | 2   |          | *FRONT BONNET SEALS-L/R            | Not Necessary         | 112.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT BONNET INSULATOR            | Not Necessary         | 189.00 FL   | *- FL        |
| 5   | 2   |          | *FRONT BONNET HINGES-L/R           | Not Necessary         | 110.00 FL   | *- FL        |
| 6   | 1   |          | *FRONT BONNET LOCK                 | Not Necessary         | 132.00 FL   | *- FL        |
| 7   | 1   |          | *FRONT BUMPER                      | Distorted             | 1,075.00 FL | *1,075.00 FL |
| 8   | 1   |          | *FRONT BUMPER LOGO                 | Necessary             | 105.00 FL   | *105.00 FL   |
| 9   | 1   |          | *FRONT BUMPER FOG LAMP-RH          | Not Necessary         | 285.00 FL   | *- FL        |
| 10  | 1   |          | *FRONT BUMPER FOG LAMP COVER       | Not Necessary         | 89.00 FL    | *- FL        |
| 11  | 1   |          | *FRONT BUMPER LOWER SEAL           | Distorted             | 116.00 FL   | *116.00 FL   |
| 12  | 1   |          | *FRONT BUMPER SPONGE               | Cracked               | 132.00 FL   | *132.00 FL   |
| 13  | 1   |          | *FRONT BUMPER REINFORCEMENT        | Bent                  | 895.00 FL   | *895.00 FL   |
| 14  | 1   |          | *FRONT BUMPER SIDE RETAINERS-L/R   | O/s Damaged           | 90.00 FL    | *45.00 FL    |
| 15  | 1   |          | *FRONT BUMPER UNDERCOVER           | Not Necessary         | 189.00 FL   | *- FL        |
| 16  | 1   |          | *FRONT FENDER-RH                   | Distorted             | 786.00 FL   | *786.00 FL   |
| 17  | 1   |          | *FRONT FENDER INNER SHIELD         | Torn                  | 146.00 FL   | *146.00 FL   |
| 18  | 1   |          | *FRONT FENDER WHEEL HOUSING ASSY   | Buckled               | 1,150.00 FL | *1,150.00 FL |
| 19  | 1   |          | *FRONT FENDER TOP GARNISH          | Cracked               | 82.00 FL    | *82.00 FL    |
| 20  | 1   |          | *FRONT DOOR-RH                     | Repair                | 1,580.00 FL | *- FL        |
| 21  | 1   |          | *FRONT DOOR SIDE MIRROR            | Damaged               | 635.00 FL   | *635.00 FL   |
| 22  | 1   |          | *FRONT DOOR SIDE MIRROR COVER      | Missing               | 182.00 FL   | *182.00 FL   |
| 23  | 2   |          | *FRONT LOWER ARMS-L/R              | Bent                  | 1,160.00 FL | *1,160.00 FL |
| 24  | 2   |          | *FRONT KNUCKLE ARMS                | Damaged               | 1,086.00 FL | *1,086.00 FL |
| 25  | 2   |          | *FRONT WHEEL HUBS                  | Damaged               | 578.00 FL   | *578.00 FL   |
| 26  | 2   |          | *FRONT WHEEL BEARINGS              | Damaged               | 370.00 FL   | *370.00 FL   |
| 27  | 1   |          | *FRONT DRIVE SHAFT-RH              | Not Necessary         | 1,360.00 FL | *- FL        |
| 28  | 1   |          | *FRONT ANTI ROLL BAR               | Not Necessary         | 365.00 FL   | *- FL        |
| 29  | 2   |          | *FRONT ANTI ROLL BAR LINKS         | Not Necessary         | 210.00 FL   | *- FL        |
| 30  | 1   |          | *FRONT STEERING RACK ASSY          | Not Necessary         | 1,892.00 FL | *- FL        |
| 31  | 1   |          | *FRONT STEERING RACK CROSSMEMBER   | Not Necessary         | 1,865.00 FL | *- FL        |
| 32  | 1   |          | *FRONT GRILLE-TOP                  | Cracked               | 265.00 FL   | *265.00 FL   |
| 33  | 1   |          | *FRONT GRILLE-LOWER                | Not Necessary         | 282.00 FL   | *- FL        |
| 34  | 1   |          | *AIR CLEANER RESONATOR             | Not Necessary         | 195.00 FL   | *- FL        |
| 35  | 1   |          | *FRONT HEADLAMP-RH                 | Cracked               | 935.00 FL   | *935.00 FL   |
| 36  | 1   |          | *REAR DOOR-RH                      | Dented                | 1,560.00 FL | *1,560.00 FL |
| 37  | 1   |          | *REAR DOOR OUTER HANDLE            | Repair                | 192.00 FL   | *- FL        |
| 38  | 1   |          | *REAR FENDER-RH                    | Distorted             | 1,895.00 FL | *1,895.00 FL |
| 39  | 1   |          | *REAR AXLE BEAM                    | Not Necessary         | 2,650.00 FL | *- FL        |
| 40  | 2   |          | *REAR WHEEL HUB BEARINGS           | Not Necessary         | 910.00 FL   | *- FL        |
| 41  | 1   |          | *REAR WINDSCREEN MOULDING          | Not Necessary         | 132.00 FL   | *- FL        |
| 42  | 1   |          | *REAR BUMPER                       | Not Necessary         | 1,075.00 FL | *- FL        |
| 43  | 1   |          | *SET F/R SPORT SHOCK ABSORBER ASSY | Bent                  | 1,500.00 FS | *1,000.00 FS |
| 44  | 2   |          | *FRONT SPORT WHEELS-L/R            | N/s Bent/O/s Cut      | 900.00 FS   | *900.00 FS   |
| 45  | 2   |          | *FRONT TYRES-L/R                   | N/s Punctured/O/s Cut | 600.00 FS   | *400.00 FS   |
| 46  | 1   |          | *TIN AUTO TX FLUID                 | Necessary             | 120.00 FS   | *50.00 FS    |
| 47  | 1   |          | *BOT POWER STEERING FLUID          | Necessary             | 60.00 FS    | *40.00 FS    |
| 48  | 1   |          | *SET REAR WINDSCREEN SEALANT       | Necessary             | 80.00 FS    | *60.00 FS    |
| 49  | 2   |          | *REAR SPORT WHEELS-L/R             | Not Necessary         | 900.00 FS   | *- FS        |
| 50  | 2   |          | *FRONT TYRES-L/R                   | Repeated              | 600.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                  |
|----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$)</b>                                    | <b>33,237.00</b> | <b>17,010.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | <b>2,847.70</b>  | <b>1,456.00</b>  |
| <b>Total Parts (\$)</b>                                  | <b>30,389.30</b> | <b>15,554.00</b> |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. |     |          |             |           |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                           | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                       |          |                 |                 |
| 1                               | TO CHECK FRONT & REAR ELECTRICAL WIRING               | New      | 80.00           | 30.00           |
| 2                               | TOWING CHARGES-2 TRIPS                                | New      | 240.00          | 60.00           |
| 3                               | TO REMOVE,REFIX FRONT UNDERCARRIAGE                   | New      | 650.00          | 500.00          |
| 4                               | TO REMOVE,REFIX REAR UNDERCARRIAGE                    | New      | 350.00          | 0.00            |
| 5                               | TO CHECK WHEEL ALIGNMENT                              | New      | 120.00          | 80.00           |
| 6                               | TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR  | New      | 120.00          | 60.00           |
| 7                               | TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS        | New      | 180.00          | 0.00            |
| 8                               | TO RESPRAY UNDERCOATING                               | New      | 60.00           | 60.00           |
| 9                               | TO RESPRAY PAINTING AND ETC                           | New      | 1,800.00        | 1,400.00        |
| 10                              | PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS | New      | 3,000.00        | 1,600.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                       |          | <b>6,600.00</b> | <b>3,790.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >