



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CENTRAL NARCOTICS BUREAU (MHA09)			Ref:	CC2/CNB21009523/Geq2
CORPORATE SERVICES DIVISION			Date:	12/11/2021
BLK B				
POLICE CANTONMENT COMPLEX				
393 NEW BRIDGE ROAD				
SINGAPORE 088763				
			Code:	CNB
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 8395M	Veh. Inspected	SLD 9473X
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	Mohamad Juahir Ismail	Assign Date	10/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JM6BM42A8G0345412	Colour	BLUE
	Odometer	202526 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	FALKEN	6 mm
	L/H Front Tyre	205/60 R16	FALKEN	6 mm
	R/H Rear Tyre	205/60 R16	FALKEN	6 mm
	L/H Rear Tyre	205/60 R16	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/09/2021	Inspection Date	10/09/2021
	Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9473X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	925.10	925.10
1	FRONT BUMPER RETAINER RH	DEFORMED	38.70	38.70
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
10	FRONT TOP PANEL RIVET	NOT NECESSARY	100.00	-
1	HEADLAMP RH	CUT	773.30	773.30
1	FRONT GRILLE TOP PANEL (NPA)	NOT NECESSARY	-	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-377.42	-357.42
			1,509.68	1,429.68
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		600.00	400.00
	TO RESPRAY AFFECTED AREAS .		600.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
			1,230.00	830.00
GRAND TOTAL			2,739.68	2,259.68
RECOMMENDED COST OF REPAIRS				2,259.68

Report Ref No. CC2/CNB21009523/Geq2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 9473X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 9473X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

