

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB21009524/KQF3N2**Date:** 21/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJQ5107K	Insured Vehicle No :	SLK4122E
Date of Loss:	04/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003897

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ5107K		
Make & Model:	HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)	Engine No:	G4FC9U654699
Reg. Date:	15/05/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U761074
Colour:	Metallic Brown	Odometer:	200426 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 1 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,648.24	1,662.64	985.60	37.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,245.00	965.00	43.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,858.24	2,907.64	1,950.60	40.15
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	4,858.24	2,300.00	2,558.24	52.66

INSPECTION

Date of Assignment:	10/09/2021	
Date Inspected:	13/09/2021	Inspected At: Kien Cheong Automotive (HQ) BLK 9 SIN MING INDUSTRIAL ESTATE #01-26 Singapore 575644
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2021)

Parts: 143 HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJQ5107K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	484.00 FL	*484.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Serviceable	96.00 FL	*- FL
3	1		*REAR BUMPER BEAM	Cracked	215.80 FL	*215.80 FL
4	2		*REAR LH TAIL LAMP	Serviceable	596.00 FL	*- FL
5	1		*REAR TAILGATE	Bent	1,391.00 FL	*851.00 FL
6	1		*REAR TAILGATE LOGO	Necessary	56.50 FL	*56.50 FL
7	1		*REAR TAILGATE EMBLEM AVANTE	Necessary	48.50 FL	*48.50 FL
8	1		*REAR TAILGATE EMBLEM S	Necessary	24.60 FL	*24.60 FL
9	1		*REAR TAILGATE INNER LOCK	Dented	85.40 FL	*85.40 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*REVERSE SENSOR	Dented/Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,247.80	2,015.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	599.56	353.16
Total Parts (\$\$)	2,648.24	1,662.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT AND TRANSFER OF TAILGATE COMPONENT	New	90.00	50.00
2	CHECK WIRING	New	50.00	15.00
3	TO REMOVE,REFIX REVERSE SENSOR	New	120.00	50.00
4	ANTI RUST	New	150.00	30.00
5	PANEL BEAT,REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	500.00
6	TO RE-SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$\$)			2,210.00	1,245.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >