

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009525/R1RS3Q2
Date: 05/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070178246
Claimant Vehicle No :	PC7994E	Insured Vehicle No :	YN3538B
Date of Loss:	08/09/2021	Nature of Claim:	TP
		Claim No:	3548800928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7994E		
Make & Model:	HIGER KLQ6128K, 9.5 D (M)	Engine No:	WP10H375E623618J047554
Reg. Date:	06/03/2019 (Man. Year: 2018)	Chassis No:	LKLR1LSL8JA738014
Colour:	White	Odometer:	143139 km
Engine Capacity:	9511 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Wind Power 8 mm	Rear Left Side:	Wind Power 8/8 mm
Front Right Side:	Wind Power 8 mm	Rear Right Side:	Wind Power 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	913.00	821.70	91.30	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	250.00	150.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,313.00	1,071.70	241.30	18.38
+ GST 7.00/7.00% (S\$)	91.91	75.02	16.89	18.38

Nett Amount (S\$)		1,404.91	1,146.72	258.19	18.38
Global Sum Settlement (S\$)			0.00		

INSPECTION

Date of Assignment:	10/09/2021		
Date Inspected:	13/09/2021	Inspected At:	The One Holdings Pte Ltd (HQ) 8 Woodlands Industrial Park E3 Singapore 757786
Estimated Period of Repair:	1.0 days		

Adjuster:	MOHD RASUL	Manager:	Jaslin Kok Chin Yi
------------------	------------	-----------------	--------------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS WING MIRROR UNIT	Cracked	913.00 F	*913.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	913.00 913.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 91.30
					Total Parts (\$)	913.00 821.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY LABOUR TO DISMANTLE AND FIXED BACK NEW UNIT OF RHS WING MIRROR .REALIGN ALL NECESSARYS	New	250.00	150.00
2	TO SPRAY UNIT	New	150.00	100.00
Gross Labour Cost (S\$)			400.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >