

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Ref	:	CS3/LPC21009526/Vtf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date	e:	17/09/2021	
			Cod	le:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	5025S	Veh. Inspected		FBH 2962U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC40/024928	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		10/09/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	SYM GTS200	c.c		172	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	RFGLM18WXDS002249	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	110/90 R13	PIRELLI		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	130/70 R13	PIRELLI		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	CHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT DN.				
5.	General Information					
	Accident Date	06/09/2021	Inspect Date / Time	<del>)</del>	10/09/2021 ( 04:26 PM )	
	Survey held at	EQUATOR BROTHERHOOD				
		25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21009526/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser