

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009528/UQCN2**Date:** 30/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00066912100

Claimant Vehicle No : SMU9616A **Insured Vehicle No :** GBC1609Z

Date of Loss: 09/09/2021 Nature of Claim: TP Claim No: SNM21D205108/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU9616A**

Make & Model: MERCEDES-BENZ GLB200, 1.3 (A) Engine No: 28291480304860

Reg. Date: 08/09/2020 (Man. Year: 2020) Chassis No: W1N2476872W030850

Colour: Blue Odometer: 13213 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R19 Rear Tyre Size: 235/50 R19

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,974.54	3,471.21	11,503.33	76.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	920.00	2,950.00	76.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,844.54	4,391.21	14,453.33	76.70
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	18,844.54	3,500.00	15,344.54	81.43

INSPECTION

Date of Assignment: 14/09/2021

Date Inspected: 13/09/2021 Inspected At: Blk 15 Kaki Bukit Road 4,
Bartley Biz Centre, #01-53
Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLB200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU9616A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed/Torn	1,786.40 FL	*1,291.84 FL
2	2	*REAR BUMPER SIDE RETAINER	Not Necessary	264.00 FL	*- FL
3	1	*REAR BUMPER INNER RETAINER	Cracked	352.80 FL	*281.21 FL
4	1	*REAR BUMPER LOWER	Torn	1,278.50 FL	*745.25 FL
5	1	*REAR BUMPER CHROME MOULDING	Cracked	1,086.70 FL	*690.00 FL
6	2	*REAR BUMPER REFLECTOR	Not Necessary	394.80 FL	*- FL
7	1	*REAR BUMPER SCUFF PLATE	Cracked	278.60 FL	*278.60 FL
8	4	*REAR BUMPER DISTANCE SENSOR	Serviceable	789.60 FL	*- FL
9	1	*SET REAR BUMPER DISTANCE SENSOR BRACKET	Not Necessary	72.60 FL	*- FL
10	1	*SET REAR BUMPER CLIPS	Necessary	65.00 FL	*50.00 FL
11	2	*TAILLAMP (LED)	Not Necessary	2,556.40 FL	*- FL
12	1	*TAILGATE	Not Necessary	2,650.40 FL	*- FL
13	1	*TAILGATE LOGO	Not Necessary	124.50 FL	*- FL
14	1	*TAILGATE EMBLEM (GLB 200)	Not Necessary	176.80 FL	*- FL
15	2	*TAILGATE LAMP (LED)	Not Necessary	1,975.20 FL	*- FL
16	1	*TAILGATE WEATHERSTRIP	Not Necessary	395.80 FL	*- FL
17	1	*REAR END PANEL TOP GARNISH TRIM	Not Necessary	368.40 FL	*- FL
18	1	*REAR END PANEL	Repair	1,086.70 FL	*- FL
19	1	*REAR BUMPER DIFFUSER	Cut	537.40 FL	*520.00 FL
20	1	*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
21	1	*REAR TAILGATE GLASS INNER SEAL,SPONGE TAPE,CLIPS	Not Necessary	118.00 FS	*- FS
22	1	*REAR TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS
23	1	*REAR NUMBER PLATE W/BASE GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,598.60	3,856.90
- List Item Discount on L Items 10.00/10.00% (S\$)	1,624.06	385.69
Total Parts (S\$)	14,974.54	3,471.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	450.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	0.00
5	TO REMOVE & INSTALL REAR FENDERS TRIM,GARNISH,SPARE TYRE COMPARTMENT	New	150.00	0.00
6	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	50.00
7	TO RE-PROGRAMME & RE-SET STAR DIAGNOSTICS	New	450.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (\$\$)			3,870.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >