

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/III21009529/ERA3Q2

**Date:**

08/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MCV0005290\_01

**Claimant Vehicle No :** SJN5558H**Insured Vehicle No :**

PC2871J

Date of Loss: 10/09/2021

Nature of Claim:

TP

Claim No:

MCV2021D0003933

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJN5558H**

Make &amp; Model: HYUNDAI AVANTE, 1.6 HD (A)

Engine No:

G4FC8U566900

Reg. Date: 20/02/2009 (Man. Year: 2008)

Chassis No:

KMHDU41BR9U648915

Colour: Red

Odometer:

170055 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Tourador 4 mm

Rear Left Side:

Tourador 4 mm

Front Right Side: Tourador 4 mm

Rear Right Side:

Tourador 4 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,111.20	2,043.20	1,068.00	34.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,730.00	580.00	25.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,421.20</b>	<b>3,773.20</b>	<b>1,648.00</b>	<b>30.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		

(S\$)	5,421.20	3,000.00	2,421.20	44.66
<b>+ GST 7.00/7.00% (S\$)</b>	379.48	210.00	169.48	44.66
<b>Nett Amount (S\$)</b>	<b>5,800.68</b>	<b>3,210.00</b>	<b>2,590.68</b>	<b>44.66</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,572.00</b>		

INSPECTION

Date of Assignment: 10/09/2021

Date Inspected: 13/09/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)  
 38 Toh Guan Road East, #01-57, Enterprise Hub  
 Singapore 608581

**Adjuster:** CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2021)
<b>Parts:</b>	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJN5558H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,000.00 FL	*947.00 FL
2	1		*REAR DOOR OUTER HANDLE LONG RH	Repair	65.00 FL	*- FL
3	1		*REAR DOOR OUTER HANDLE SMALL RH	Repair	22.00 FL	*- FL
4	1		*REAR FENDER RH	Dented	1,207.00 FL	*1,207.00 FL
5	1		*REAR BUMPER	Repair	450.00 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	70.00 FL	*- FL
7	1		*REAR BUMPER CLIPS	Not Necessary	35.00 FS	*- FS
8	1		*REAR FENDER SHIELD CLIPS RH	Not Necessary	25.00 FS	*- FS
9	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
10	1		*REAR FENDER SEALANT RH	Necessary	60.00 FS	*30.00 FS
11	1		*REAR RIM 15 INCH RH	Cut	680.00 FS	*250.00 FS
					<b>Sub Total (\$\$)</b>	<b>3,674.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>562.80</b>
					<b>Total Parts (\$\$)</b>	<b>3,111.20</b>
						<b>2,043.20</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	800.00	700.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEM & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	600.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
4	CHECK AND WHEEL COMPUTERIZE ALIGNMENT	New	80.00	60.00
5	TO REMOVE AND REFIX FRONT TYRE AND WHEEL BALANCING IN ORDER TO REAR RIM LH	New	50.00	20.00
6	TO REMOVE AND REPLACE REAR DOOR RH FITTING ,TRIMMINGS ,GARNISH ,WINDOW GLASS AND MECHANISM	New	100.00	50.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN	New	120.00	120.00
8	TO REMOVE AND REFIT REAR SEAT IN ORDER TO REPAIR	New	100.00	50.00
9	TO REMOVE AND REFIT /REPLACE ROOTS LINING & UPHOLSTER GARNISH	New	100.00	50.00
10	TO REMOVE AND REPLACE REAR QUARTER GLASS RH	New	100.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>2,310.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >