

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009532/TQCN2**Date:** 22/02/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00005242111

Claimant Vehicle No : JGJ4651**Insured Vehicle No :** SJN214H

Date of Loss: 30/08/2021

Nature of Claim: TP

Claim No: SNM21D204876/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **JGJ4651**

Make & Model: YAMAHA RXZ, 133cc (M)

Engine No: HIDDEN

Reg. Date: 02/01/2002 (Man. Year: 2001)

Chassis No: ZMC263059

Colour: Red

Odometer: 39806 km

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/90R18	Rear Tyre Size:	90/90R18
Front Left Side:	FKR 5 mm	Rear Left Side:	FKR 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,380.90	4,451.20	1,929.70	30.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	730.00	1,420.00	66.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,530.90	5,181.20	3,349.70	39.27
Approved Total (Overridden) (\$\$)		2,700.00		
(\$\$)	8,530.90	2,700.00	5,830.90	68.35
+ GST 7.00/7.00% (\$\$)	597.16	189.00	408.16	68.35
Nett Amount (\$\$)	9,128.06	2,889.00	6,239.06	68.35

INSPECTION

Date of Assignment: 15/09/2021

Date Inspected: 14/09/2021 Inspected At:

Em-1 Auto Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate Sector C, #01-68

Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Feb 2022)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JGJ4651)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT WING MIRROR	Cut	164.00 FL	*164.00 FL
2	2		*HANDLE BAR ASSY	Bent	250.00 FL	*250.00 FL
3	2		*HANDLE BAR HOLDER RUBBER	Cut	112.00 FL	*112.00 FL
4	2		*HANDLE BAR HOLDER JOINT	Cut	32.00 FL	*32.00 FL
5	1		*HAND BRAKE LEVER RH	Cut	55.00 FL	*55.00 FL
6	1		*HAND CLUTCH LEVER LH	Cut	55.00 FL	*55.00 FL
7	1		*HAND CLUTCH LEVER CABLE LH	Bent	85.00 FL	*85.00 FL
8	1		*BRAKE PUMP ASSY	Cracked	255.00 FL	*255.00 FL
9	1		*BRAKE PUMP PIPE	Cut	85.00 FL	*85.00 FL
10	1		*SET FRONT HORN	Bent	120.00 FL	*120.00 FL
11	1		*SET METER ASSY	Cracked	460.00 FL	*460.00 FL
12	1		*METER CABLE	Not Necessary	92.00 FL	*- FL
13	1		*HEADLAMP ASSY	Cracked	290.00 FL	*290.00 FL
14	1		*HEADLAMP SWITCH ASSY	Not Necessary	165.00 FL	*- FL
15	1		*FRONT SIDE LAMPS	O/s Missing/N/s Not Necessary	178.00 FL	*89.00 FL
16	1		*FRONT COWLING	Cracked	192.00 FL	*192.00 FL
17	1		*FRONT COWLING OUTER GARNISH COVER	Cracked	115.00 FL	*115.00 FL
18	1		*SET FRONT COWLING BRACKET	Bent	106.00 FL	*106.00 FL
19	1		*FRONT FENDER	Cracked	149.00 FL	*149.00 FL
20	2		*FRONT FORK ASSY	Bent	904.00 FL	*600.00 FL
21	1		*FRONT FORK CENTER BRACKET	Not Necessary	136.00 FL	*- FL
22	1		*FRONT FORK TOP BRACKET	Not Necessary	159.00 FL	*- FL
23	2		*FRONT FORK WHEEL BEARING	Not Necessary	180.00 FL	*- FL
24	1		*FRONT WHEEL BEARING SHAFT	Dented	125.00 FL	*125.00 FL
25	1		*FRONT BRAKE DISC	Not Necessary	365.00 FL	*- FL
26	1		*FRONT BRAKE CALIPER	Dented	412.00 FL	*212.00 FL
27	1		*SET FRONT BRAKE PAD	Necessary	50.00 FL	*30.00 FL
28	1		*REAR EXHAUST PIPE	Dented	325.00 FL	*325.00 FL
29	1		*SIDE STAND LH	Not Necessary	105.00 FL	*- FL
30	1		*FOOT BRAKE LEVEL RH	Bent	92.00 FL	*92.00 FL
31	1		*STARTER BAR RH	Bent	125.00 FL	*125.00 FL
32	1		*STARTER BAR TRIANGLE BRACKET BOLT	Not Necessary	18.00 FL	*- FL
33	1		*REAR SIDE BODY COWLING COVER RH	Cracked	265.00 FL	*265.00 FL
34	1		*BTL FRONT FORK ASSY OIL	Not Necessary	50.00 FS	*- FS
35	1		*SET BODY COWLING STICKER	Necessary	220.00 FS	*120.00 FS
36	1		*REAR NUMBER PLATE	Bent	12.00 FS	*12.00 FS
37	1		*ENGINE OIL	Not Necessary	80.00 FS	*- FS
38	1		*REAR LUGGAGE BOX	Cut	400.00 FS	*350.00 FS
39	1		*STARTER BAR TRIANGLE BRACKET BOLT	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,003.00	4,890.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	622.10	438.80
Total Parts (\$\$)	6,380.90	4,451.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	250.00
2	SPRAY PAINTING	New	600.00	300.00
3	CHECK WIRING	New	20.00	20.00
4	REMOVE AND INSTALL FRONT AND REAR UNDERCARRIAGE	New	250.00	120.00
5	REMOVE AND INSTALL EXHAUST PIPE	New	80.00	40.00
6	TO JACK AND ALIGN BODY CHASSIS FRAME	New	500.00	0.00
Gross Labour Cost (\$)			2,150.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >