

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	TITANIUM LAW C	HAMBERS LLC	Ref:	CS/LAW21009535/T1vce2
	180 CECIL STREE BUILDING, SINGA	T, #11-02, BANGKOK BANK PORE 069546	Date:	05/10/2021
			Code:	L174
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
	Insured Veh.	YP 617R	Veh. Inspected	SGV 4868M
	Policy No.		Coverage (\$)	0.00
	Claim No.	AWE/FDK/III/1286	Excess (\$)	0.00
	Assign From	Fendrick Koh	Assign Date	10/09/2021
2.	Vehicle Particulars & Condition			
	Make & Model	B.M.W. 523I XL	c.c	2497
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	WBANU120X0CW23148	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
4.	Description of Damages			
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
5.	General Information			
	Accident Date	15/11/2019	Inspection Date	13/09/2021
	Survey held at	889 CAR SERVICING PTE LTD		
		10 KAKI BUKIT ROAD 2 #03-34 FIRST EAST CENTRE SINGAPORE 417868		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			