

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009545/GPA3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800095561
<b>Claimant Vehicle No :</b>	SJP5636E	<b>Insured Vehicle No :</b>	SJV2055U
Date of Loss:	23/08/2021	Nature of Claim:	TP
		Claim No:	6745134452SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJP5636E</b>	Engine No:	G4FC9U618809
Make & Model:	HYUNDAI HD AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U712943
Reg. Date:	28/03/2009 (Man. Year: 2009)	Odometer:	98605 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,584.16	897.04	687.12	43.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	860.00	620.00	41.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,064.16</b>	<b>1,757.04</b>	<b>1,307.12</b>	<b>42.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>(S\$)</b>	3,064.16	1,400.00	1,664.16	54.31
<b>+ GST 7.00/7.00% (S\$)</b>	214.49	98.00	116.49	54.31
<b>Nett Amount (S\$)</b>	<b>3,278.65</b>	<b>1,498.00</b>	<b>1,780.65</b>	<b>54.31</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	10/09/2021	
Date Inspected:	25/10/2021	Inspected At: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Buckled	996.30 FL	*996.30 FL
2	1		*REAR RH DOOR OUTER MOULDING	Not Necessary	65.00 FL	*- FL
3	1		*REAR RH DOOR OUTER MOULDING		-	-
4	1		*REAR RH DOOR RUBBER	Not Necessary	113.90 FL	*- FL
5	1		*REAR RH DOOR OUTER HANDLE	Not Necessary	68.00 FL	*- FL
6	1		*REAR RH SPORT RIM (LOCAL REPAIR)	Scratched	273.60 FS	*100.00 FS
7	1		*REAR RH WHEEL BEARING	Not Necessary	395.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,911.80	1,096.30
- List Item Discount on L Items 20.00/20.00% (\$)	327.64	199.26
Total Parts (\$)	1,584.16	897.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
2	TO REPAIR DAMAGES	New	580.00	300.00
3	TO SPRAY PAINTING	New	780.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,480.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >