

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009548/KRS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900109834
Claimant Vehicle No :	SJX2317D	Insured Vehicle No :	SMM8472X
Date of Loss:	05/09/2021	Nature of Claim:	TP
		Claim No:	7858963656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2317D	Engine No:	ZY591648
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM0DE10Y1A0148528
Reg. Date:	26/05/2010 (Man. Year: 2009)	Odometer:	122473 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/45 R16	Rear Tyre Size:	195/45 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,460.84	2,426.28	34.56	1.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,100.00	500.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,060.84	3,526.28	534.56	13.16
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,060.84	2,800.00	1,260.84	31.05
+ GST 7.00/7.00% (S\$)	284.26	196.00	88.26	31.05
Nett Amount (S\$)	4,345.10	2,996.00	1,349.10	31.05
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Medical Costs (S\$)		438.10		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,676.10		

INSPECTION

Date of Assignment:	10/09/2021	
Date Inspected:	14/09/2021	Inspected At: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,033.20 FL	*1,033.20 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	36.40 FL	*18.20 FL
3	10		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	272.80 FL	*272.80 FL
5	1		*TAILGATE	Bent	1,243.50 FL	*1,243.50 FL
6	1		*EMBLEM MAZDA	Necessary	29.20 FL	*29.20 FL
7	1		*EMBLEM 2	Necessary	20.50 FL	*20.50 FL
8	1		*EMBLEM MAZDA BADGE	Necessary	44.20 FL	*44.20 FL
9	1		*REVERSE SENSOR	Dented	220.00 FS	*200.00 FS
10	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
11	2		*WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$)	3,004.80 2,966.60
					- List Item Discount on L Items 20.00/20.00% (\$)	543.96 540.32
					Total Parts (\$)	2,460.84 2,426.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND INSTALL REVERSE SENSOR	New	20.00	20.00
2	TO DISMANTLE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
3	TO DISMANTLE AND REPLACE TAILGATE TRANSFER TAIL GATE INNER PARTS WIRING HANESS AND TRIM BOARD	New	60.00	60.00
4	TO DISMANTLE AND INSTALL DAMAGED PARTS ,TO KNOCK AND REPAIR TAIL END PANEL AND AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME	New	700.00	400.00
5	TO SPRAY TAILGATE ,REAR BUMPER ,TAIL END PANEL AND REAR BUMPER REINFORCEMENT	New	700.00	500.00
Gross Labour Cost (\$\$)			1,600.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >