

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009554/ARS3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000003227
Claimant Vehicle No :	SJD2577A	Insured Vehicle No :	SDJ8278M
Date of Loss:	11/09/2021	Nature of Claim:	TP
		Claim No:	2538582246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD2577A	Engine No:	1ZZ2929447
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	ZNE100370965
Reg. Date:	14/03/2008 (Man. Year: 2007)	Odometer:	209770 km
Colour:	Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,970.54	3,348.94	1,621.60	32.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,810.00	590.00	24.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,370.54	5,158.94	2,211.60	30.01
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	7,370.54	4,100.00	3,270.54	44.37
+ GST 7.00/7.00% (S\$)	515.94	287.00	228.94	44.37
Nett Amount (S\$)	7,886.48	4,387.00	3,499.48	44.37
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,063.45		

INSPECTION

Date of Assignment:	13/09/2021	Ryder Auto Pte Ltd (HQ)
Date Inspected:	13/09/2021 Inspected At:	2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	881.66 FL	*524.00 FL
2	8		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
3	2		*REAR BUMPER O/S & N/S STAY	Not Necessary	85.80 FL	*- FL
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	234.60 FL	*120.00 FL
5	2		*REAR O/S & N/S REFLECTOR	Not Necessary	124.60 FL	*- FL
6	1		*REAR TAIL GATE	Dented	1,217.30 FL	*1,217.30 FL
7	1		*REAR TAIL GATE WEATHERSTRIP	Not Necessary	289.90 FL	*- FL
8	1		*REAR TAIL GATE EMBLEM	Necessary	81.70 FL	*81.70 FL
9	1		*REAR TAIL GATE MOULDING CHROME	Not Necessary	387.72 FL	*- FL
10	6		*REAR TAIL GATE MOULDING CLIPS	Not Necessary	30.00 FS	*- FS
11	1		*REAR TAIL GATE INNER TRIM	Cracked	591.75 FL	*485.00 FL
12	8		*REAR TAIL GATE INNER TRIM CLIPS	Necessary	40.00 FS	*30.00 FS
13	1		*REAR TAIL GATE LOCK (UPPER)	Damaged	322.70 FL	*322.70 FL
14	1		*REAR TAIL GATE LOCK (LOWER)	Not Necessary	124.80 FL	*- FL
15	1		*REAR END PANEL	Dented	455.65 FL	*455.65 FL
16	1		*REAR END PANEL INNER TRIM	Deformed	289.90 FL	*289.90 FL
17	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
18	1		*REAR O/S & N/S TAIL LAMP	N/S Cracked	845.98 FL	*409.00 FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS
20	1		*REAR WINDSCREEN MOULDING	Necessary	80.00 FS	*80.00 FS
21	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*230.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,454.06	4,325.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,483.52	976.31
Total Parts (\$\$)	4,970.54	3,348.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PORTION ,STRAIGHTEN & WELDING	New	1,200.00	800.00
2	TO SPRAY PAINTIING	New	800.00	700.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	50.00	50.00
5	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	50.00	50.00
6	TO CHECK WIRING	New	80.00	30.00
7	TO RE-SEAL ANTI RUST	New	80.00	60.00
Gross Labour Cost (\$\$)			2,400.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >