

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009559/UEA3Q2
Date: 20/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100450769
Claimant Vehicle No :	SKP1398G	Insured Vehicle No :	SKZ7371R
Date of Loss:	12/09/2021	Nature of Claim:	TP
		Claim No:	3531480030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP1398G	Engine No:	G4FGEH730697
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFX411MF5303702
Reg. Date:	18/08/2014 (Man. Year: 2014)	Odometer:	107296 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,440.00	7,664.20	11,775.80	60.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	2,980.00	2,070.00	40.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,490.00	10,644.20	13,845.80	56.54
Approved Total (Overridden) (S\$)		8,500.00		

	(S\$)	24,490.00	8,500.00	15,990.00	65.29
	+ GST 7.00/7.00% (S\$)	1,714.30	595.00	1,119.30	65.29
	Nett Amount (S\$)	26,204.30	9,095.00	17,109.30	65.29
	+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
	+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)		9,582.45		
	Global Sum Settlement (S\$)		9,580.00		

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 13/09/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,661.00 F	*1,491.00 FL
2	2		*BOOTLID HINGES	Repair	300.00 F	*- FL
3	1		*BOOTLID REAR LOGO	Necessary	85.00 F	*45.00 FL
4	1		*BOOTLID CERATO EMBLEM	Necessary	68.00 F	*42.00 FL
5	1		*BOOTLID FORTE EMBLEM	Necessary	60.00 F	*40.00 FL
6	1		*BOOTLID K3 EMBLEM	Necessary	52.00 F	*40.00 FL
7	1		*BOOTLID C&C LOGO	Necessary	50.00 F	*50.00 FL
8	1		*BOOTLID INNER LOCK	Twisted	199.00 F	*112.00 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	281.00 F	*182.00 FL
10	2		*BOOTLID REFLECTORS	Not Necessary	1,450.00 F	*- FL
11	1		*BOOTLID INNER TRIM	Not Necessary	281.00 F	*- FL
12	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
13	1		*REAR BUMPER	Distorted	1,250.00 F	*688.00 FL
14	1		*REAR BUMPER LOWER GARNISH	Distorted	650.00 F	*315.00 FL
15	1		*REAR BUMPER REFLECTORS	N/S Cracked	176.00 F	*48.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	120.00 F	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	515.00 F	*495.00 FL
18	2		*REAR BUMPER REINFORCEMENT BRACKETS	Dented	360.00 F	*290.00 FL
19	3		*REAR BUMPER REINFORCEMENT TOP BRACKETS	Cracked	75.00 F	*75.00 FL
20	2		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Cracked	50.00 F	*50.00 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
22	1		*REAR END PANEL	Badly Dented	691.00 F	*451.00 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	288.00 F	*188.00 FL
24	2		*TAILLAMPS	Cracked	2,100.00 F	*1,210.00 FL
25	2		*TAILLAMP HOUSING PANELS	Repair	900.00 F	*- FL
26	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,420.00 F	*1,145.00 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped	615.00 F	*385.00 FL
28	2		*REAR FENDERS	Repair	3,300.00 F	*- FL
29	2		*REAR FENDER INNER TRIMS	Deformed / Torn	710.00 F	*524.00 FL
30	1		*REAR EXHAUST	Repair	745.00 F	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Bent	122.00 F	*122.00 FL
32	1		*REAR WINDSCREEN MOULDING	Not Necessary	86.00 F	*- FL
33	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
36	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*180.00 FS	
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS	
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS	
					Sub Total (\$\$)	19,440.00	8,468.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	803.80
					Total Parts (\$\$)	19,440.00	7,664.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISN	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	120.00	100.00
6	TO RESET & REPROGRAMME SYSTEM	New	100.00	0.00
7	TO DISMANTLE & REPLACED REAR EXHAUST	New	100.00	60.00
8	TO MOUNT VEHIVCLE ON CAR O-LINER	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,000.00	1,400.00
10	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,200.00
			Gross Labour Cost (S\$)	5,050.00
				2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >