

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009560/UQC2**Date:** 23/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00010492100		
<b>Claimant Vehicle No :</b>	SMZ5467M	<b>Insured Vehicle No :</b>	CB6747T		
Date of Loss:	02/09/2021	Nature of Claim:	TP	Claim No:	SNM21D204986/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMZ5467M</b>		
Make & Model:	M.G. HS, 1.5 (A)	Engine No:	15E4E8AGLC020169
Reg. Date:	30/04/2021 (Man. Year: 2020)	Chassis No:	LSJA24U95MN021948
Colour:	Blue	Odometer:	6972 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	418.00	418.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	360.00	180.00	180.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>778.00</b>	<b>598.00</b>	<b>180.00</b>	<b>23.14</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	54.46	41.86	12.60	23.14
<b>Nett Amount (\$\$)</b>	<b>832.46</b>	<b>639.86</b>	<b>192.60</b>	<b>23.14</b>

**INSPECTION**

Date of Assignment:	12/09/2021		
Date Inspected:	14/09/2021	Inspected At:	Auto Bay@ Kaki Bukit Avenue 6 Entrance A #01-04
Estimated Period of Repair:	1.0 days		Repairer: Kt Garage Pte Ltd

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2021)
Parts:	M1-SUV	M.G. HS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ5467M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE MIRROR ASSEMBLY (WCP)	Cracked	380.00 F	*380.00 F
						F=Franchise part.
					Sub Total (S\$)	380.00 380.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	38.00 38.00
					Total Parts (S\$)	418.00 418.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE AND RENEW THE ABOVE PARTS	New	180.00	100.00
2	TO SPRAY PAINT ALL AFFECTED AREAS	New	180.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>360.00</b>	<b>180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >