

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21009561/GGA3Q2**Date:** 13/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_01

Claimant Vehicle No : SMH564T **Insured Vehicle No :** SMV6493B

Date of Loss: 08/09/2021 Nature of Claim: TP Claim No: MFL2021D0004071

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH564T**
 Make & Model: MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A) Engine No: PE21251169
 Reg. Date: 09/01/2019 (Man. Year: 2018) Chassis No: JM6GL1072K0311314
 Colour: Blue Odometer: 32913 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,101.73	5,149.76	2,951.97	36.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	870.00	670.00	43.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,641.73	6,019.76	3,621.97	37.57
+ GST 7.00/7.00% (S\$)	674.92	421.38	253.54	37.57
Nett Amount (S\$)	10,316.65	6,441.14	3,875.51	37.57
+ Car Rental (5.0 x S\$140.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		7,219.14		

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 20/09/2021 Inspected At:

Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
 Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @
 KAKI BUKIT
 Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2022)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH564T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,454.40 FL	*1,026.50 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Cut	24.50 FL	*24.50 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	24.50 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP CHROME RH	Cut	79.20 FL	*79.20 FL
5	1		*FRONT FENDER RH	Repair	460.80 FL	*- FL
6	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	138.10 FL	*- FL
7	1		*FRONT HEADLAMP RH	Scratched	5,712.30 FL	*4,758.60 FL
8	1		*FRONT HEADLAMP LOWER CHROME RH	Cut	302.40 FL	*211.20 FL
9	1		*FRONT BUMPER SENSOR	Damaged	200.00 FS	*200.00 FS
10	1		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
11	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
12	1		*FRONT BUMPER BRACKET RH	Cut	37.20 FL	*37.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,513.40	6,377.20
- List Item Discount on L Items 5.00/20.00% (\$\$)	411.67	1,227.44
Total Parts (\$\$)	8,101.73	5,149.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	80.00	40.00
2	TO DISCONNECT AND RECONNECT CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS REPLACE DAMAGED PARTS	New	30.00	30.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	600.00	400.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	New	80.00	0.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	100.00	0.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	0.00
7	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	500.00	400.00
Gross Labour Cost (\$\$)			1,540.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >