| | xt |
|--|----|
|--|----|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationals Dea Synapta En Automobile | | | | | | | |
|---|---|--|----------------|-------|----------------------|--|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | | |
| | EQ INSURANCE C | | | Ref: | CS3/EQI21009562/Ntf3 | | |
| | 5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI | | | Date: | 13/09/2021 | | |
| | | | | Code: | EQI | | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | | |
| | Insured Veh. | GBE 9399R | Veh. Inspected | d | SDD 5443R | | |
| | Policy No. | | Coverage (\$) | | 0.00 | | |
| | Claim No. | DM21HO01349-JG | Excess (\$) | | 0.00 | | |
| | Assign From | JOEL GOH | Assign Date | | 13/09/2021 | | |
| 2. | Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | | |
| | Engine No. | HIDDEN | Year of Reg. | | | | |
| | Chassis No. | | Colour | | | | |
| | Odometer - Steering | | | | | | |
| | Brakes Modification | | | | | | |
| | General | | | | | | |
| 3. Conditions of Tyres | | | | | | | |
| | | Size | Make | | Balance | | |
| | R/H Front Tyre | | | | mm | | |
| | L/H Front Tyre | | | | mm | | |
| | R/H Rear Tyre | | | | mm | | |
| | L/H Rear Tyre | | | | mm | | |
| 4. | Description of Damages | | | | | | |
| | | | | | | | |
| 5. | | General | Information | | | | |
| | Accident Date | 10/09/2021 | Inspection Da | te | 16/09/2021 | | |
| | Survey held at | Survey held at SIN SENG HONG SPRAY PAINTING & SERVICES | | | | | |
| | | BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716 | | | | | |
| 5a. | a. Remarks | | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | | |