

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21009564/AGA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0006336  
**Claimant Vehicle No :** SJD64B **Insured Vehicle No :** FBS8350M  
 Date of Loss: 11/09/2021 Nature of Claim: TP Claim No: MCV2021D0003927

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD64B**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Standard (A) Engine No: 1ZR0A88078  
 Reg. Date: 21/02/2018 (Man. Year: 2018) Chassis No: MR053REH604578605  
 Colour: Red Odometer: 57225 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,125.28	2,702.50	2,422.78	47.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,440.00	1,410.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,975.28</b>	<b>4,142.50</b>	<b>3,832.78</b>	<b>48.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		
<b>(S\$)</b>	7,975.28	3,300.00	4,675.28	58.62
<b>+ GST 7.00/7.00% (S\$)</b>	558.27	231.00	327.27	58.62
<b>Nett Amount (S\$)</b>	<b>8,533.55</b>	<b>3,531.00</b>	<b>5,002.55</b>	<b>58.62</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,938.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,900.00</b>		

INSPECTION

Date of Assignment: 13/09/2021  
 Date Inspected: 13/09/2021 Inspected At: Ryder Auto Pte Ltd (HQ)  
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit  
 Singapore 417921  
 Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 23 Jan 2022)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 Standard (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJD64B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	681.40 FL	*585.00 FL
2	1		*REAR BUMPER N/S REFLECTOR	Not Necessary	128.60 FL	*- FL
3	1		*REAR BUMPER N/S RETAINER	Cracked	98.60 FL	*55.00 FL
4	1		*REAR N/S TAIL -LAMP	Cracked	582.10 FL	*355.00 FL
5	1		*REAR N/S TAIL -LAMP RETAINER	Cracked	280.30 FL	*45.00 FL
6	1		*REAR N/S TAIL-LAMP PANEL	Dented	563.80 FL	*374.00 FL
7	1		*REAR N/S TAIL-LAMP SEAL	Necessary	30.00 FL	*20.00 FL
8	1		*REAR N/S FENDER	Dented	1,336.80 FL	*981.00 FL
9	1		*REAR N/S FENDER WHEEL GUARD	Deformed	163.80 FL	*55.00 FL
10	1		*REAR N/S FENDER AIR VENT	Not Necessary	205.60 FL	*- FL
11	1		*REAR N/S RIM	Cut	1,508.03 FS	*700.00 FS
12	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
13	1		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
14	2		*REAR REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
15	1		*REAR N/S FENDER WHEEL GUARD CLIPS	Necessary	24.00 FS	*10.00 FS
16	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,143.03</b>	<b>3,320.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,017.75	617.50
<b>Total Parts (\$\$)</b>	<b>5,125.28</b>	<b>2,702.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,400.00	600.00
2	TO SPRAY PAINTING	New	1,000.00	600.00
3	TO REMOVE & REFIT REAR WINDSCREEN REAR SEATS & ROOF LINING	New	280.00	120.00
4	TO REMOVE & REPLACE REAR REVERSE SENSOR CAMERA	New	50.00	50.00
5	TO REMOVE & REFIT REAR N/S TYRE (NPA)	New	0.00	0.00
6	TO CHECK WIRING	New	60.00	30.00
7	TO RE-SEAL ANTI-RUST	New	60.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>2,850.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >