

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21009565/Vtf3e2
	300 BEACH ROAD		Date:	20/10/2021
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		1.000
				: LPC2
1.	, , , , , , , , , , , , , , , , , , , ,			
	Insured Veh.	XE 329S	Veh. Inspected	FBN 5073J
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VC00/024921	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	13/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA SNIPER T150	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MH3UG0740J0126193	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	BRIDGESTONE	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	BRIDGESTONE	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	AND N/S BODY.	
5.	General Information			
	Accident Date	01/09/2021	Inspect Date / Time	13/09/2021 (03:24 PM)
	Survey held at	BEAR'S GARAGE LLP		
		25 KAKI BUKIT ROAD 4 #03-62 SYNERGY@KB SINGAPORE 417800		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC21009565/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser