

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21009568/APA3Q2**Date:** 07/01/2022**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0005721
<b>Claimant Vehicle No :</b>	SNA3986P	<b>Insured Vehicle No :</b>	SJF9332H
Date of Loss:	11/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003929

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNA3986P</b>	Engine No:	F318H911B38A15A
Make & Model:	MINI ONE, 1.5 5DR HB (LCI) (A)	Chassis No:	WMWXU52020TH95922
Reg. Date:	21/12/2018 (Man. Year: 2018)	Odometer:	18709 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,804.14	4,120.01	11,684.13	73.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,510.00	2,850.00	65.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,164.14</b>	<b>5,630.01</b>	<b>14,534.13</b>	<b>72.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		

<b>Nett Amount (S\$)</b>	<b>20,164.14</b>	<b>4,500.00</b>	<b>15,664.14</b>	<b>77.68</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,107.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,100.00</b>		

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 13/09/2021

Estimated Period of Repair: 5.0 days

Inspected At: SM Automotive (HQ)  
756 JURONG WEST STREET 74, #12-60  
Singapore 640756

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
<b>Parts:</b> 144	MINI ONE 1.5 5DR HB (LCI) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNA3986P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	986.10 FL	*986.10 FL
2	1		*REAR BUMPER REINFORCEMENT GARNISH LH	Cracked	294.20 FL	*294.20 FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	117.20 FL	*- FL
4	1		*REAR BUMPER TOW COVER	Damaged	68.10 FL	*68.10 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	224.50 FL	*- FL
6	1		*REAR BUMPER LOWER LIP	Deformed	680.40 FL	*325.00 FL
7	1		*REAR BUMPER LAMP	Cracked	354.50 FL	*354.50 FL
8	1		*REAR BUMPER LAMP OUTER CHROME	Cracked	98.50 FL	*98.50 FL
9	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,382.00 FL	*500.00 FL
10	4		*REAR BUMPER REVERSE SENSOR COVER	Necessary	220.00 FL	*100.00 FL
11	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	921.80 FL	*- FL
12	1		*REAR TAILGATE	Repair	1,087.40 FL	*- FL
13	1		*REAR TAILGATE LOCK CATCH	Not Necessary	58.60 FL	*- FL
14	1		*REAR TAILGATE LOCK MOTOR	Not Necessary	586.70 FL	*- FL
15	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	254.50 FL	*- FL
16	1		*REAR BUMPER EMBLEM ONE	Necessary	58.50 FL	*58.50 FL
17	1		*REAR WEATHERSTRIPE	Not Necessary	266.30 FL	*- FL
18	1		*REAR TAILGATE OUTER CHROME MOULDING	Not Necessary	354.60 FL	*- FL
19	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	589.60 FL	*- FL
20	1		*REAR TAILLAMP	N/S Cracked	1,178.80 FL	*589.40 FL
21	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	120.10 FL	*- FL
22	1		*REAR TAILLAMP OUTER CHROME MOULDING	N/S Cracked	241.40 FL	*120.70 FL
23	1		*REAR END PANEL	Repair	689.50 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	190.20 FL	*- FL
25	1		*REAR END PANEL AIR VENT	Not Necessary	164.50 FL	*- FL
26	1		*REAR END PANEL AIR DUCT	Deformed	85.90 FL	*85.90 FL
27	1		*REAR FLOOR PANEL	Not Necessary	684.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	341.50 FL	*- FL
29	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	224.60 FL	*- FL
30	1		*REAR FLOOR PANEL UNDER COVER	Not Necessary	194.20 FL	*- FL
31	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	968.20 FL	*- FL
32	2		*REAR FENDER INNER COWLING	Not Necessary	373.00 FL	*- FL
33	2		*REAR FENDER OUTER GARNISH	Not Necessary	709.20 FL	*- FL
34	1		*REAR EXHAUST MUFFLER	Repair	796.14 FS	*100.00 FS
35	1		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	43.20 FL	*- FL
36	1		*REAR EXHAUST MUFFLER HEAT SHIELD	Crumpled	324.60 FL	*125.00 FL
37	1		*REAR BUMPER REINFORCEMENT	Bent	583.00 FL	*583.00 FL
38	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
39	1		*REAR TAILLAMP CLIPS	Necessary	40.00 FS	*10.00 FS
40	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS
42	2		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*REAR TAILGATE STICKER	Necessary	400.00 FS	*120.00 FS
44	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>17,376.14</b>	<b>4,548.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,572.00	428.89
<b>Total Parts (\$)</b>	<b>15,804.14</b>	<b>4,120.01</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING	New	1,600.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,400.00	600.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	50.00
5	LABOUR FOR REMOVE & TRANSFER REAR TAILGATE FITTING	New	350.00	0.00
6	LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS	New	150.00	0.00
7	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE	New	300.00	80.00
8	TO PERFORM DIAGNOSTIC TEST	New	180.00	150.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,360.00</b>
				<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >