

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009570/UEA3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
<b>Claimant Vehicle No :</b>	SJT9411P	<b>Insured Vehicle No :</b>	GBK4160M
Date of Loss:	11/09/2021	Nature of Claim:	TP
		Claim No:	7838285744SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJT9411P</b>	Engine No:	2358941
Make & Model:	DAIHATSU TERIOS, 1.5 4WD (A)	Chassis No:	JDAJ210G001102179
Reg. Date:	10/11/2009 (Man. Year: 2009)	Odometer:	164880 km
Colour:	Grey		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,960.01	5,092.60	7,867.41	60.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	2,520.00	1,050.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,530.01</b>	<b>7,612.60</b>	<b>8,917.41</b>	<b>53.95</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>16,530.01</b>	<b>6,000.00</b>	<b>10,530.01</b>	<b>63.70</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (\$\$)</b>		700.00		
<b>+ Doc/Search Fee (\$\$)</b>		36.45		
<b>Nett Liability (\$\$)</b>		<b>6,736.45</b>		

INSPECTION

Date of Assignment:	13/09/2021		
Date Inspected:	13/09/2021	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	7.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,377.10 FL	*850.00 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Bent	168.40 FL	*49.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FL	*50.00 FL
4	1		*TAILLAMP	O/S Cracked	972.20 FL	*305.00 FL
5	1		*TAILGATE	Badly Dented	1,680.25 FL	*885.00 FL
6	1		*TAILGATE LOGO	Necessary	98.50 FL	*52.00 FL
7	1		*TAILGATE EMBLEM (TERIOS)	Necessary	115.40 FL	*66.00 FL
8	1		*TAILGATE EMBLEM (4WD)	Necessary	128.10 FL	*60.00 FL
9	1		*TAILGATE EMBLEM (DAIHATSU)	Necessary	125.40 FL	*58.00 FL
10	1		*TAILGATE INNER LOCK	Not Necessary	118.20 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	245.90 FL	*222.00 FL
12	2		*TAILGATE HINGE	Not Necessary	243.00 FL	*- FL
13	1		*TAILGATE INNER TRIMBOARD	Deformed/ Cracked	780.10 FL	*355.00 FL
14	1		*SPARE TYRE OUTER GARNISH COVER	Cracked	1,459.30 FL	*1,215.00 FL
15	1		*SPARE TYRE INNER GARNISH COVER	Cracked	535.70 FL	*499.00 FL
16	1		*SPARE TYRE BRACKET	Repair	385.60 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH TRIM	Not Necessary	368.40 FL	*- FL
18	1		*REAR END PANEL INNER	Repair	1,089.20 FL	*- FL
19	1		*REAR END PANEL OUTER	Badly Dented	945.36 FL	*485.00 FL
20	1		*REAR FLOOR PANEL	Repair	1,177.68 FL	*- FL
21	1		*REAR FENDER INNER TRIM BOARD O/S	Deformed / Torn	585.64 FL	*405.00 FL
22	1		*REAR EXHAUST PIPE	Repair	937.80 FL	*- FL
23	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
24	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*REAR TAILGATE GLASS INNER SEAL ,SPONGE TAPE	Necessary	118.00 FS	*30.00 FS
26	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
27	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
28	1		*REAR NUMBER PLATE LAMP	Cracked	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,320.23</b>	<b>5,926.00</b>
<b>- List Item Discount on L Items 10.00/15.00% (\$)</b>	1,360.22	833.40
<b>Total Parts (\$)</b>	<b>12,960.01</b>	<b>5,092.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	1,000.00
2	TO PUTTY SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	1,100.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	80.00
5	TO REMOVE & INSTALL REAR FENDERS TRIM GARNISH ,SPARE TYRE COMPARTMENT	New	150.00	80.00
6	TO REMOVE & INSTALL REAR TAILGATE GLASS TO FACILITATE REPAIRS	New	150.00	120.00
7	TO RE-POSITION & ALIGN REVERSE SENSOR	New	120.00	50.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>3,570.00</b>	<b>2,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >