



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202782

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/05/2022
Reference CC6/CTI21009572/Eea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 9835E
Insured Veh. SKR 4615A
Claim No. SNM21D205177/C02
Policy No. DMHCSNW00007182100
Accident Date 11/09/2021
Inspection Date 13/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref:	CC6/CTI21009572/Eea3q2
3 ANSON ROAD #16-00			Date:	17/05/2022
SPRINGLEAF TOWERSINGAPORE 079909			Code:	CTI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 4615A	Veh. Inspected	SLE 9835E	
Policy No.	DMHCSNW00007182100	Coverage (\$)	0.00	
Claim No.	SNM21D205177/C02	Excess (\$)	0.00	
Assign From		Assign Date	13/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850HX200406	Colour	PURPLE	
Odometer	69078 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	5 mm	
L/H Front Tyre	185/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2021	Inspection Date	13/09/2021	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 9835E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	680.00	492.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER RETAINER RH	BROKEN	30.00	30.00
1	REAR BUMPER RETAINER LH	BROKEN	30.00	30.00
1	REAR ANTENNA	BROKEN	150.00	118.00
1	REAR TAIL LAMP RH	CUT	480.00	480.00
1	REAR TAIL LAMP LH	BROKEN	480.00	480.00
1	REAR FENDER LH	DENTED	780.00	780.00
1	REAR FENDER INNER TRIM LH	CRUSHED	300.00	260.00
1	REAR FENDER SHIELD LH	CRUSHED	80.00	80.00
1	REAR FENDER SHIELD RH	NOT NECESSARY	80.00	-
10	REAR FENDER SHIELD CLIPS @\$5.00	NECESSARY	50.00	20.00
1	REAR FENDER GLASS LH MOULDING	NOT NECESSARY	100.00	-
1	REAR AIR VENT LH	MISSING	50.00	50.00
1	REAR HONDA EMBLEM	NECESSARY	50.00	50.00
1	REAR JAZZ EMBLEM	NECESSARY	50.00	50.00
1	TAILGATE DOOR	DENTED	1,000.00	832.00
1	TAILGATE DOOR LOCK	BENT	150.00	150.00
1	TAILGATE DOOR LATCH	NOT NECESSARY	50.00	-
1	TAILGATE DOOR RUBBER SEAL	CRUSHED	120.00	120.00
1	TAILGATE DOOR INNER TRIM	CRUSHED	180.00	180.00
1	TAILGATE HINGE ABSORBER RH	NOT NECESSARY	170.00	-
1	TAILGATE HINGE ABSORBER LH	NOT NECESSARY	170.00	-
1	TAILGATE CHROME GARNISH	NOT NECESSARY	240.00	-
1	REAR WINDSCREEN MOULDING (TOP,BTM ,RH,LH)	NECESSARY	200.00	131.00
1	END PANEL	DENTED	580.00	393.00
1	END PANEL GARNISH	CRUSHED	150.00	107.00
1	REAR SPARE TYRE BOARD	CRUSHED	250.00	250.00
1	REAR SPARE TYRE PANEL (SINK)	DENTED	800.00	800.00
1	REAR SPARE TYRE SPONGE	CRUSHED	200.00	200.00
1	TYRE SINK STIFFENER (ADDITIONAL)	DENTED	250.00	250.00

Report Ref No. CC6/CTI21009572/Eea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FRAME STIFFENER LH (ADDITIONAL)	DENTED	180.00	180.00
1	REAR FRAME END LH (ADDITIONAL)	NOT NECESSARY	50.00	-
1	REAR FRAME LH (ADDITIONAL)	NOT NECESSARY	80.00	-
1	REAR FRAME COMPLETE LH (ADDITIONAL)	DENTED	780.00	650.00
1	REAR FENDER RH (ADDITIONAL)	TO REPAIR SEE LABOUR	780.00	-
1	REAR FENDER GLASS MOULDING RH (ADDITIONAL)	NOT NECESSARY	100.00	-
1	REAR EXHAUST COVER (ADDITIONAL)	BROKEN	80.00	80.00
1	REAR ABSORBER COVER LH (ADDITIONAL)	TORN	50.00	50.00
1	REAR FENDER GUTTER PANEL RH (ADDITIONAL)	TO REPAIR SEE LABOUR	150.00	-
1	REAR FENDER GUTTER PANEL LH (ADDITIONAL)	DENTED	150.00	150.00
1	REAR BUZZER (ADDITIONAL)	BROKEN	150.00	55.00
1	ANTENNA (UNDER REAR SEAT) (ADDITIONAL)	NOT NECESSARY	100.00	-
1	ANTENNA COVER (UNDER REAR SEAT) (ADDITIONAL)	BROKEN	120.00	80.00
	LESS 20% DISCOUNT		-	-1,521.60
			10,720.00	6,086.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALAN (SN)	NECESSARY	40.00	40.00
1	REAR FENDER GLASS LH SEALANT (SN)	NECESSARY	40.00	20.00
1	REAR LICENSE PLATE WITH FRAME (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	BROKEN	200.00	200.00
1	REAR FENDER GLASS LH SEALANT (SN) (ADDITIONAL)	REPEATED	20.00	-
			340.00	260.00
	<u>LABOUR</u>			
	SPRAY PAINTING (TAILGATE,REAR BUMPER ,2 REAR FENDERS & 2 REAR DOORS ,ROOF RAILING LH).		1,500.00	1,300.00
	REPAIR ,REPLACE ,REFIT AND REPAIR ACCIDENT AFFECTED AREAS .		800.00	200.00
	CUT ,WELD ,REALIGN REAR FENDER LH .		600.00	500.00
	CUT,WELD ,REALIGN END PANEL AND SPARE TYRE SINK.INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR FENDER GUTTER PANEL RH .		1,000.00	800.00
	REPAIR REAR FENDER INNER PANEL LH .		300.00	200.00

Report Ref No. CC6/CTI21009572/Eea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	MOUNT VEHICLE ON CHASSIS JIG AND REALIGN CHASSIS TO SPEC.		300.00	200.00
	REMOVE & REFIT UPHOLSTERY ,GARNISHES ,TRIMMING TO FACILITATE REPAIR.		150.00	80.00
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR .		100.00	30.00
	REMOVE AND REFIT REAR EXHAUST PIPE AND SILENCER ,RE-ALIGN.		80.00	50.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR .	NOT NECESSARY	80.00	-
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	100.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		120.00	120.00
	REMOVE AND REFIT REAR FENDER GLASS LH.		80.00	50.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	50.00
	WHEEL ALIGNMENT.		100.00	60.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
	REPAIR REAR FENDER INNER PANEL RH .(ADDITIONAL)		300.00	200.00
	REPAIR REAR FLOOR CROSSMEMBER (REAR SEAT ROW) .(ADDITIONAL)		300.00	200.00
	CUT ,WELD ,RE-ALIGN REAR FENDER LH.(ADDITIONAL)	NOT NECESSARY	500.00	-
	REMOVE AND REFIT REAR UNDERCARRIAGE LH .(ADDITIONAL)	NOT NECESSARY	180.00	-
	REMOVE AND REFIT REAR FENDER GLASS RH .(ADDITIONAL)	NOT NECESSARY	50.00	-
			6,770.00	4,070.00
GRAND TOTAL			17,830.00	10,416.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,350.00

Report Ref No. CC6/CTI21009572/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 9835E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 9835E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 9835E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

