

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |                   |                 |                        |  |
|---|--|-------------------|-----------------|------------------------|--|
|   | AXA INSURANCE  | PTE LTD           | Ref:            | CC4/ASM21009581/Ara3q2 |  |
|   | 8 SHENTON WAY<br>AXA TOWERSING   |                   | Date:           | 20/12/2021             |  |
|   | ATTN:KITTY TEO   |                   | Code:           | ASM                    |  |
| 1.  | . Policy Particulars :- THIRD PARTY CLAIM  |                   |                 |                        |  |
|   | Insured Veh.   | SHC 3680G         | Veh. Inspected  | SGT 138Z               |  |
|   | Policy No.   | P2419138          | Coverage (\$)   | 0.00                   |  |
|   | Claim No.  | S1M03HS6          | Excess (\$)     | 0.00                   |  |
|   | Assign From  |                   | Assign Date     | 13/09/2021             |  |
| 2. Vehicle Particulars & Condition                                |  |                   |                 |                        |  |
|   | Make & Model   | B.M.W. 528I       | c.c             | 1997                   |  |
|   | Engine No.   | HIDDEN            | Year of Reg.    | 2013                   |  |
|   | Chassis No.  | WBAXG32050D121945 | Colour          | BLACK                  |  |
|   | Odometer   | 107251 KM         | Steering        | IN ORDER               |  |
|   | Brakes   | IN ORDER          | Modification    | SPORTS RIM             |  |
|   | General  | GOOD              |                 |                        |  |
| 3.  | 3. Conditions of Tyres   |                   |                 |                        |  |
|   |  | Size              | Make            | Balance                |  |
|   | R/H Front Tyre   | 245/45 R18        | CONTINENTAL     | 6 mm                   |  |
|   | L/H Front Tyre   | 245/45 R18        | CONTINENTAL     | 6 mm                   |  |
|   | R/H Rear Tyre  | 245/45 R18        | CONTINENTAL     | 6 mm                   |  |
|   | L/H Rear Tyre  | 245/45 R18        | CONTINENTAL     | 6 mm                   |  |
| 4.  | Description of Damages   |                   |                 |                        |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                   |                 |                        |  |
|   | DAMAGES SEE DETAILS.   |                   |                 |                        |  |
| 5.  | General Information  |                   |                 |                        |  |
|   | Accident Date  | 11/09/2021        | Inspection Date | 13/09/2021             |  |
|   | Survey held at   | CN MOTORS PTE LTD |                 |                        |  |
|   | 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 41788  |                   |                 |                        |  |
| 5a.   | Remarks  |                   |                 |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                   |                 |                        |  |
| 5b.   | Estimate Days of Repair  |                   |                 |                        |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days   |                   |                 |                        |  |
|   |  |                   |                 |                        |  |