

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009588/KES3Q2
Date: 15/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210010684
Claimant Vehicle No :	SLZ6733A	Insured Vehicle No :	SNA7733B
Date of Loss:	10/09/2021	Nature of Claim:	TP
		Claim No:	3898528347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6733A		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	LEB6318361
Reg. Date:	18/07/2017 (Man. Year: 2017)	Chassis No:	GP71115069
Colour:	Metallic Dark Grey	Odometer:	253738 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	RAPID 8 mm	Rear Left Side:	RAPID 7 mm
Front Right Side:	RAPID 8 mm	Rear Right Side:	RAPID 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,130.71	2,142.37	2,988.34	58.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,215.00	1,365.00	52.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,710.71	3,357.37	4,353.34	56.46
Approved Total (Overridden) (S\$)		2,650.00		

Nett Amount (S\$)	7,710.71	2,650.00	5,060.71	65.63
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,957.45		

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 14/09/2021

Estimated Period of Repair: 4.0 days

Inspected At: Ngs Automotive (HQ)
BLK 10 AMK IND PK 2A #02-01
Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	984.51 FL	*984.51 FL
2	1		*WEATHERSTRIP ,TAILGATE (50%)	Cut / Dented	142.56 FS	*89.10 FS
3	1		*LOCK ,TAILGATE	Dented	236.80 FL	*236.80 FL
4	1		*POCKET ,TAILGATE	Serviceable	28.10 FL	*- FL
5	1		*END PANEL	Repair	459.03 FL	*- FL
6	1		*REAR BUMPER	Buckled	890.80 FL	*890.80 FL
7	2		*REAR BUMPER SIDE RETAINER RH/LH	Serviceable	45.60 FL	*- FL
8	1		*TOW COVER	Serviceable	21.95 FL	*- FL
9	2		*TAILGATE LAMP RH/LH	Serviceable	799.80 FL	*- FL
10	2		*TAILLAMP RH/LH	Serviceable	1,540.60 FL	*- FL
11	2		*GROMMET LOWER ,TAILLAMP RH/LH	Not Necessary	11.76 FL	*- FL
12	2		*GROMMET UPPER ,TAILLAMP RH/LH	Not Necessary	11.76 FL	*- FL
13	1		*TAILGATE BADGE	Necessary	32.75 FL	*32.75 FL
14	1		*EMBLEM SHUTTLE	Necessary	52.00 FL	*52.00 FL
15	1		*EMBLEM HYBRID	Necessary	61.70 FL	*61.70 FL
16	1		*PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
17	2		*REAR BUMPER CLIPS	Necessary	6.42 FS	*6.42 FS
18	1		*NO PLATE C/W CASING	Serviceable	50.00 FS	*- FS
19	1		*SEALANT	Necessary	60.00 FS	*40.00 FS
20	20		*CLIPS ,RR FENDER SHIELD	Not Necessary	70.00 FS	*- FS
21	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,166.14	2,594.08
- List Item Discount on L Items 20.00/20.00% (\$)	1,035.43	451.71
Total Parts (\$)	5,130.71	2,142.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT /ATTACHMENT .STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PARTS .REFIT INTO POSITION	New	1,200.00	500.00
2	REMOVE REAR WINDSCREEN & TRANSFER TO NEW TAILGATE	New	180.00	120.00
3	TRANSFER DOOR MECHANISM	New	150.00	60.00
4	TO SPRAY PAINTING	New	1,000.00	520.00
5	CHECK WIRING & LIGHT FUNCTION	New	50.00	15.00
Gross Labour Cost (\$)			2,580.00	1,215.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >