

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009589/KVCN2**Date:** 29/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00006792100

Claimant Vehicle No : SJW5880D**Insured Vehicle No :** SJG895D

Date of Loss: 06/09/2021

Nature of Claim: TP

Claim No: SNM21D205141/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJW5880D**Make & Model: MITSUBISHI LANCER, 1.5 MIVEC A/T ELEGANCE
2WD 4DR (A)

Engine No: 4A910127136

Reg. Date: 01/04/2010 (Man. Year: 2009)

Chassis No: JMYSRCY2AAU000550

Colour: Metallic White

Odometer: 207263 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**

Front Tyre Size: 225/45ZR17

Rear Tyre Size: 225/45ZR17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,095.20	1,128.80	966.40	46.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	765.00	625.00	44.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,485.20	1,893.80	1,591.40	45.66
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	3,485.20	1,500.00	1,985.20	56.96
+ GST 7.00/7.00% (\$\$)	243.96	105.00	138.96	56.96
Nett Amount (\$\$)	3,729.16	1,605.00	2,124.16	56.96

INSPECTION

Date of Assignment: 13/09/2021

Date Inspected: 14/09/2021 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Oct 2021)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC A/T ELEGANCE 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW5880D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	731.00 FL	*731.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Serviceable	36.00 FL	*- FL
3	1		*REAR BUMPER CENTRE BEAM	Repair	82.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Buckled/Distorted	552.00 FL	*233.00 FL
5	2		*REAR BUMPER REFLECTOR	Serviceable	52.00 FL	*- FL
6	1		*REAR BUMPER TOW HOOK COVER	Dented	20.00 FL	*20.00 FL
7	1		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
8	1		*REAR END PANEL	Repair	407.00 FL	*- FL
9	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
10	1		*REAR NUMBER PLATE	Serviceable	30.00 FS	*- FS
11	1		*REAR NUMBER PLATE HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,288.00	1,232.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	192.80	103.20

Total Parts (\$\$)	2,095.20	1,128.80
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE FOR PANEL BEATING AND REPLACE ALL DAMAGED PARTS	New	600.00	300.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
3	APPLY ANTI-RUST	New	60.00	0.00
4	TO REMOVE/REFIT REVERSE SENSOR	New	80.00	50.00
5	CHECK WIRING AND LIGHTS	New	50.00	15.00
Gross Labour Cost (\$\$)			1,390.00	765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >