1/3/22, 11:08 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG21009597/AGS3Q2

Date:

03/01/2022

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

1900129532 SLB7540J

Claimant Vehicle No:

SMN9260D 10/09/2021

Insured Vehicle No: Nature of Claim:

TP

Claim No:

0487221601SG

WAUZZZ8V1KA114424

CHZC32325

17486 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN9260D

Make & Model: AUDI A3, 1.4 TFSI S-TRONIC (A)

Reg. Date: 31/08/2019 (Man. Year: 2019)

Colour: Grev

Engine Capacity: 999 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size:

205/55 R16

Front Left Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,460.00	1,555.20	1,904.80	55.05
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,422.00	1,522.00	900.00	37.16
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	5,882.00	3,077.20	2,804.80	47.68
	+ GST 7.00/7.00% (S\$)	411.74	215.40	196.34	47.69

Nett Amount (S\$)	6,293.74	3,292.60	3,001.14	47.68
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	3,444.60		

INSPECTION

Date of Assignment: 13/09/2021

Premium Automobiles Pte Ltd (UBI) Date Inspected: 15/09/2021

55 Ubi Road 1 Inspected At: Singapore 408699

Estimated Period of Repair: 3.0 days

ADRIAN LING Adjuster: Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	1	*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2 ′	1	*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*-FS
3	1	*REAR BUMPER ADAPTER	Not Necessary	38.00 FS	*-FS
4 2	2	*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	32.00 FS	*-FS
5	1	*REAR BUMPER SPOILER	Not Necessary	237.00 FS	*-FS
6	1	*REAR LIGHT REFLECTOR -LH	Not Necessary	41.00 FS	*-FS
7 ′	1	*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 FS	*-FS
8 2	2	*REAR BUMPER BRACKET -LH/RH	Not Necessary	58.00 FS	*-FS
9 2	2	*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*-FS
10 4	1	*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*-FS
11 ′	1	*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Franc	chise part. S=SpcNett.				
			Total Parts (S\$)	3,460.00	1,555.20

Report was unsubmitted during this print-out.

1/3/22, 11:08 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >