3/17/22, 12:49 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009604/VEA3Q2

17/03/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210079411

Claimant Vehicle SHD4431Y Insured Vehicle No: SNB2909P No:

Date of Loss: 12/09/2021 Nature of Claim: TP Claim No: 6134163694SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD4431Y**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) G4LEKU410423 Engine No:

Reg. Date: 19/12/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU190345

Colour: Odometer: 223432 km Blue

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 5 mm West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,550.92	1,611.28	1,939.64	54.62
Miscellaneous Items		0.00	0.00	0.00	
Labour		750.00	630.00	120.00	16.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,300.92	2,241.28	2,059.64	47.89
	+ GST 7.00/7.00% (S\$)	301.06	156.89	144.17	47.89
	Nett Amount (S\$)	4,601.98	2,398.17	2,203.81	47.89
	+ Loss of Use (2.0 x	S\$50.00/day) (S\$)	100.00		
	+ Car Rental (2.0 x S	\$125.19/day) (S\$)	250.38		
	+ Do	c/Search Fee (S\$)	7.49		
		Nett Liability (S\$)	2,756.04		
	Global Sui	m Settlement (S\$)	2,750.00		

INSPECTION

Date of Assignment: 13/09/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 14/09/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: Asher Sng Rong Yi

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Repair	430.90 FL	*- FL
2	1		*GRILLE ASSY -RADIATOR	Scratched	1,598.60 FL	*1,598.60 FL
3	1		*MOULDING -FRONT BUMPER CTR	Scratched	368.50 FL	*368.50 FL
4	1		*LAMP ASSY -HEAD RH	Serviceable	1,993.65 FL	*- FL
5	1		*BRACKET -FR BUMPER SIDE RH	Necessary	25.00 FL	*25.00 FL
6	10		*BUMPER COVER CLIP FRONT	Necessary	22.00 FL	*22.00 FL
F=Fra	nchise	part. L=ListIten	nDisc.	Sub Total (S\$)	4,438.65	2,014.10
			- List Item Discount on L Items	20.00/20.00% (S\$)	887.73	402.82
				Total Parts (S\$)	3,550.92	1,611.28
			Report was unsubmitted during t	his print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			*
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	CHECK ALL LIGHTING	New	50.00	30.00
		Gross Labour Cost (S\$)	750.00	630.00
	Re	eport was unsubmitted during this print-out.		

< END OF ESTIMATES >