



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 6920S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	627.20	627.20
8	FRONT BUMPER CLIPS @\$5.50	NECESSARY	44.00	44.00
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	1,052.20	-
1	FRONT FENDER HYBRID EMBLEM N/S	NOT NECESSARY	73.40	-
4	FRONT FENDER INNER COWLING CLIPS N/S @\$5.50	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-454.70	-167.80
			1,364.10	503.40
<u>LABOUR</u>				
	TO KNOCK AND STRAIGHTEN DAMAGE PANEL, CUT & WELD NECESSARY PORTION AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S.		600.00	300.00
	TO RUST PROOF ALL AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO CHECK ALL LIGHTING AND WIRING.		80.00	20.00
	TO SPRAY PAINT ALL AFFECTED AREAS.		600.00	400.00
			1,360.00	720.00
GRAND TOTAL			2,724.10	1,223.40
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				1,223.40

Report Ref No. CS/GAI21009609/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.