

Shop Name: K.KIM HIN AUTO PTE LTD

Tel: 64527018

Email: service@kkimhin.com.sg

Address: 160 SIN MING DRIVE, 02-20 ,SIN MING AUTO CITY, 575722, SINGAPORE

Shop Number: 199402370D

Vehicle information

Nissan 2010/07- Urvan

VIN:

Mileage: 139001km

Diagnostics time: 2021/09/17 10:51

Path: Manual selection > Far east > Singapore > Urvan > E25 > 2010/7 - > Diagnosis > Auto scan >

Status report

System name	DTC counts	Status
Engine	1	Fault
Air bag	0	Pass

1. Engine — (1)

1.1. P0380

GLOW relay

1. Ensure the vehicle ignition is in ON position.
2. Ensure the cable is in good condition and is securely attached to vehicle DLC.
3. Ensure the battery is fully charged.
4. Verify the system is configured for the vehicle.
5. Ensure there is a green check mark on the VCI icon of the device display.
6. Attempt to establish communication between the device and the VCI via USB cable.
7. If the problem persists, record the issue in a data log and submit to Dealer or contact Technical Support.

A close-up of a square, light-colored button with the letters "ESC" printed vertically in the center.

Shop Name: K.KIM HIN AUTO PTE LTD

Tel: 64527018

Email: service@kkimhin.com.sg

Address: 160 SIN MING DRIVE, 02-20 ,SIN MING AUTO CITY, 575722, SINGAPORE

Shop Number: 199402370D

Vehicle information

Nissan 2010/07- Urvan

VIN:

Mileage: 139001km

Diagnostics time: 2021/09/21 11:08

Path: Manual selection > Far east > Singapore > Urvan > E25 > 2010/7 - > Diagnosis > Auto scan >

Status report

System name	DTC counts	Status
Engine	0	Pass
ABS	0	Pass
Air bag	0	Pass