

9/9/21, 3:39 PM

REPAIR DETAILS

Merimen e-Claims

Reference

Part Source:

Parts: N/A (Last Synchronised: 09 Sep 2021)
 Labour: Repairer's NISSAN URVAN 3.0 SMT (A) (Model not available in database)
 Print Code: (Unsubmitted, no print-code for GBC5866X) (Price-denominated Standard List)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Contains total 'C'

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON CONDENSER FAN MOTOR	shorted	0.00	0.00
2	1		*AIR FILTER	C	0.00	0.00
3	1		*ENGINE OIL FILTER	C	0.00	0.00
4	2		*FRONT WHEEL BEARING (LH & RH)	nn	0.00	0.00
5	1		*FRONT BRAKE PAD	C	0.00	0.00
6	1		*REAR BRAKE SHOE	C	0.00	0.00
7	2		*REAR BRAKE PUMP (LH & RH)	C	0.00	0.00
8	2		*REAR WHEEL BEARING (LH & RH)	C	0.00	0.00
9	2		*REAR WHEEL BEARING OIL SEAL - INNER	nn	0.00	0.00
10	2		*REAR WHEEL BEARING OIL SEAL - OUTER	nn	0.00	0.00
11	1		*CLUTCH DISC	C	0.00	0.00
12	1		*CLUTCH COVER	C	0.00	0.00
13	1		*CLUTCH BEARING	C	0.00	0.00
14	1		*ABS PUMP	C	0.00	0.00
15	1		*ENGINE OIL (9 LIT)	C	0.00	0.00
16	1		*GEAR OIL (5 LIT)	nn	0	0.00
17	1		*AXLE OIL (3 LIT)	nn	0	0.00
18	1		*BRAKE OIL	0	0.00	nn
19	1		*FRONT NUMBER PLATE	0	0.00	nn
20	2		*FRONT DOOR COMPANY REGISTRATION STICKER	nn	0	0.00
21	1		*REAR FLOOR PANEL TOP WOODEN BASE	C	0	0.00
Sub Total (\$)						4,518.00
+ Margin on L,N Items 15.00% (\$)						496.50
Total Parts (\$)						5,014.50

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Supp

1pc Diesel filter ✓ acc 120/-
 1pc ECU Unit 'C' 950.00 ✓

Labor

To conduct programming . 8380/- ✓

9/21, 3:39 PM

Estimates on Miscellaneous Items

Merimen e-Claims

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Labour Items

Lab.Type

Amount

- 1 TO REMOVE AND WASH CARPET
- 2 TO REMOVE, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.
- 3 TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.
- 4 LABOUR TO REMOVE AND REFIX GEAR BOX FOR RENEW CLUTCH DISC.
- 5 TO TOW ACCIDENT VEHICLE TO WORKSHOP BY KING DOLLY AND WINCH OUT.

New

450.00

New

600.00

New

1,200.00

New

250.00

New

400.00

Gross Labour Cost (S\$)

2,900.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >