



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 8009T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP	SCRATCHED	380.00	265.00
1	HEADLAMP COVER	CUT	280.00	190.00
1	HANDLE BAR BRACKET	NOT NECESSARY	110.00	-
1	HANDLE BAR	BENT	125.00	125.00
2	HANDLE GRIPS L-R @\$28.50	NOT NECESSARY	57.00	-
2	HANDLE BAR BALANCER L-R @\$32.00	N/S CUT	64.00	25.00
2	MIRRORS L-R @\$65.00	N/S CUT	130.00	65.00
2	REAR FOOT REST STAY RUBBER L-R @\$32.00	NOT NECESSARY	64.00	-
2	FRONT FOOT REST STAY RUBBER L-R	NOT NECESSARY	155.00	-
1	SET FAIRING (WHOLE)	CUT / CRACKED	480.00	480.00
2	FRONT SIDE LAMP @\$85.00	NO SUCH PARTS	170.00	-
2	FRONT FORK ASSYS @\$450.00	N/S TWISTED / DAMAGED	900.00	300.00
1	FRONT FORK BRACKET	NOT NECESSARY	95.00	-
1	FRONT FENDER	CUT	95.00	95.00
1	FRONT WHEEL BEARING	NOT NECESSARY	40.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	35.00	-
1	BRAKE PUMP	NOT NECESSARY	480.00	-
1	BRAKE LEVER	NOT NECESSARY	45.00	-
1	BRAKE PEDAL	NOT NECESSARY	95.00	-
1	CLUTCH LEVER	SCRATCHED	105.00	45.00
1	GEAR PEDAL	SERVICEABLE	85.00	-
1	ENGINE MAGNET COVER	NOT NECESSARY	150.00	-
1	FRONT SPORT GEAR COVER	NO SUCH PARTS	90.00	-
1	EXHAUST	NOT NECESSARY	900.00	-
1	EXHAUST MUFFLER	NOT NECESSARY	350.00	-
1	EXHAUST MUFFLER COVER FRONT	NOT NECESSARY	85.00	-
1	EXHAUST MUFFLER COVER REAR	NOT NECESSARY	120.00	-
1	METER	NOT NECESSARY	450.00	-
1	METER COVER	NOT NECESSARY	90.00	-
1	BRAKE DISC	NOT NECESSARY	130.00	-

Report Ref No. CS/SMR21009615/Uuf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SIGNAL LAMP	N/S SCRATCHED	78.00	50.00
1	N/S REAR SIGNAL LAMP	SCRATCHED	150.00	50.00
1	RADIATOR	NOT NECESSARY	385.00	-
	LESS 10% DISCOUNT		-	-169.00
			6,968.00	1,521.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RIM (SN)	NOT NECESSARY	300.00	-
1	REAR RIM (SN)	NOT NECESSARY	300.00	-
1	SET REAR HANDLE GRIP (SN)	NOT NECESSARY	250.00	-
1	SET BODY STICKER (SN)	NOT NECESSARY	120.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	150.00	-
			1,120.00	-
	<u>LABOUR</u>			
	TOWING CHARGES.	NOT NECESSARY	50.00	-
	TO RESPRAY PAINT AND ETC.		580.00	200.00
	TO CHECK FRONT & REAR ELECTRICAL WIRING.	NOT NECESSARY	120.00	-
	TO REMOVE, REFIX AND REALIGN FRONT FORK.	NOT NECESSARY	140.00	-
	TO STRAIGHTEN, REPAIR & REALIGN CHASSIS FRAME MEMBER.	NOT NECESSARY	500.00	-
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS.		1,000.00	300.00
			2,390.00	500.00
	GRAND TOTAL		10,478.00	2,021.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/SMR21009615/Uuf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.