

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009616/ETCE2

Date: 29/09/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00126992100  
Claimant Vehicle No: SMQ7742C Insured Vehicle No: SMT7042Z  
Date of Loss: 11/09/2021 Nature of Claim: TP Claim No: SNM21D205140/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ7742C  
Make & Model: SUBARU XV, 2.0 (A) Engine No: FB20YJ85408  
Reg. Date: 30/11/2019 (Man. Year: 2019) Chassis No: JF1GT7KL5KG079455  
Colour: Red Odometer: 28525 km  
Engine Capacity: 1995 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,925.78	4,647.12	5,278.66	53.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,912.00	4,190.00	4,722.00	52.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,837.78</b>	<b>8,837.12</b>	<b>10,000.66</b>	<b>53.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,318.64</b>	<b>618.60</b>	<b>700.04</b>	<b>53.09</b>
<b>Nett Amount (S\$)</b>	<b>20,156.42</b>	<b>9,455.72</b>	<b>10,700.70</b>	<b>53.09</b>

### INSPECTION

Date of Assignment: 14/09/2021  
Date Inspected: 15/09/2021 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)  
25 Leng Kee Road  
Singapore 159097  
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,630.63 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2021)
<b>Parts:</b>	M1-SUV	SUBARU XV 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ7742C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*30.00 FS
2	1		*ARM ASSY F LH	* Check	138.20 FN	*- FN
3	1		*LINK ASSY R TRG	* Check	119.74 FN	*- FN
4	1		*LINK ASSY R LAT R	* Check	154.80 FN	*- FN
5	1		*ARM ASSY R UPR LH	* Check	432.00 FN	*- FN
6	1		*STRUT COMPL F LH	* Check	424.98 FN	*- FN
7	1		*MOUNT STRUT F	* Check	83.12 FN	*- FN
8	1		*SHOCK ABS COMPL R	* Check	207.54 FN	*- FN
9	1		*MOUNT SHOCK ABS R	* Check	92.23 FN	*- FN
10	2		*VALVE TPMS ASSY	Necessary	336.60 FN	*336.60 FN
11	1		*HOUSING F LH	* Check	209.90 FN	*- FN
12	1		*DRV SFT ASSY F 92	* Check	984.53 FN	*- FN
13	1		*HUB UNIT COMPL F	* Check	460.80 FN	*- FN
14	1		*HOUSING ASSY R ALLH	* Check	507.60 FN	*- FN
15	1		*DRV SFT ASSY R 75152	* Check	945.65 FN	*- FN
16	1		*HUB UNIT COMPL R	* Check	234.00 FN	*- FN
17	1		*FENDER F XUV LH	Repair	207.54 FN	*- FN
18	1		*BUMPER PUNCHING F	Cut	446.40 FN	*446.40 FN
19	1		*BRKT CORNER F FHILH	* Check	36.00 FN	*- FN
20	1		*BRKT SD F XUV LH	* Check	7.20 FN	*- FN
21	1		*COVER FOG F XUV LH	Cut	46.30 FN	*46.30 FN
22	1		*PNL COMPL DR F LH	Dented	920.00 FN	*920.00 FN
23	1		*PNL COMPL DR R WLH	Dented	888.00 FN	*888.00 FN
24	1		*TAPE DR SASH F F LH	Necessary	10.80 FN	*10.80 FN
25	1		*TAPE DR SASH F M LH	Necessary	10.80 FN	*10.80 FN
26	1		*TAPE DR SASH R M WLH	Necessary	7.50 FN	*7.50 FN
27	1		*GARNISH AY FENDERLH	Cut	140.00 FN	*140.00 FN
28	1		*GARNISH AY R QTR LH	Cut	140.00 FN	*140.00 FN
29	1		*FRONT UNDER SPOILER GT - ML	Not Necessary	1,032.00 FS	*- FS
30	1		*SIDE UNDER SPOILER GT LH - ML	Cut	660.00 FS	*660.00 FS
31	2		*RIM GT EDTN 18 (FRONT LH & REAR LH)	Cut	1,600.00 FS	*1,600.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,564.23</b>	<b>5,236.40</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	1,638.45	589.28
<b>Total Parts (\$\$)</b>	<b>9,925.78</b>	<b>4,647.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT 4-WHEEL ALIGNMENT	New	200.00	200.00
2	TYRE SALES OF 02PCS 225/55R18 BRIDGESTONE ALENZA	New	952.00	0.00
3	TO REPAIR AND REPLACE FRONT BUMPER, FRONT LHS FENDER, FRONT LHS DOOR, FRONT LHS DOOR, REAR LHS FENDER AND LHS UNDERSPOILER	New	3,920.00	1,680.00
4	TO RESPRAY FRONT BUMPER, FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR AND REAR LHS FENDER	New	2,640.00	1,760.00
5	TRANSFER FRONT LHS AND REAR LHS RIM AND BALANCE FRONT LHS AND REAR LHS TYRE	New	100.00	100.00
6	DISMENTLE & REFIX UNDERCARRIAGE FRONT LHS AND REAR LHS TO FACILITATE REPAIR (* Check)	New	600.00	0.00
7	TRANSFER FRONT LHS AND REAR LHS DOOR MECHANISM	New	400.00	400.00
8	TO CONDUCT WATER SEEPAGE TEST	New	100.00	50.00
9	TO SUPPLY AND REPLACE FRONT LHS AND REAR LHS TYRE (NPA) (* Check)	New	0.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,912.00</b>	<b>4,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >