

File CS/CT. 2100 9616/ETC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
at \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claim No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
I certify: The veh had commenced its  
repair at the time of inspection.



Est. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
SIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMA 7742C Yr Regn: 30/11/19  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Sabru XV C.B. 1995  
Colour: Red A/O: Insured / St / NI / N  
Sp. Reading: 28525 T/Radio: Insured / St / NI / N  
Eng/No: TF 1617 KL SK 079455  
C/No: \_\_\_\_\_  
Gen. Cond: Good / Fair / Poor / Surpt  
Steering: In order / Jammed / Locked / Burnt or  
Brakes: In order / Jammed / Locked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: Ft 225/55R15  
R: \_\_\_\_\_  
ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
F/Bbl. 4 mm R/Bbl. 4 mm  
L/Bbl. 4 mm U/Bbl. 4 mm  
D.O.A. 11/9/21 O.O.I. 15/9/21  
Survey held at Motor Image  
Det. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / CHASSIS frame / Body Structure affected due to collision

Date / Time Action / Instruction

11/9/21

SUBMIT PRELI REPORT

OWNER WITHDRAW CLAIM

Site/Time, File, Res to R. ☐ : Prel. Report

☐ : Final Report

Site/Time, File Return to?

Days Of Repair: 8

Resurvey No. of Trips: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Insp (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation

\_\_\_\_\_ \$ + P.S. \$

Printed

Signature

TOTAL

Signature

Stamp / U.S. / etc

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/0041/2021  
DATE : 11-SEP-2021

9073 2232  
Jeff

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :  
MOTOR CLAIM DEPT

OWNER'S NAME : VEENA BHAGYALAKSHMI ATEETH  
ADDRESS : APT BLK 360 TAMPINES STREET 34  
#04-413  
S(520360)  
TELEPHONE NO : 90181414

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1900252374-01  
VEHICLE NO : SMQ7742C  
MODEL CODE : GT7CKVL-KY81  
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT(KY81)  
ENGINE NO : FB20YJ85408  
CHASSIS NO : JF1GT7KL5KG079455  
MILEAGE : 1 KM  
DATE IN : 11/09/2021  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 11/09/2021

Print Date : 11/09/2021  
Print Time : 17:51:27

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ7742C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 1W0001W	TO CONDUCT 4-WHEEL ALIGNMENT	200.00	/
2 TY02	TYRE SALES OF 02PCS 225/55R18 BRIDGESTONE ALENZA	952.00	X
3 ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT LHS FENDER, FRONT LHS DOOR, FRONT LHS DOOR, REAR LHS FENDER AND LHS UNDERSPOILER	3920.00	1680
4 ZZ/002	FENDER AND LHS UNDERSPOILER		
5 ZZ/003	TO RESPRAY FRONT BUMPER, FRONT LHS FENDER, FRONT LHS DOOR, REAR LHS DOOR AND REAR LHS FENDER	2640.00	1760
6 ZZ/004	TRANSFER FRONT LHS AND REAR LHS RIM AND BALANCE FRONT LHS AND REAR LHS TYRE	100.00	/
7 ZZ/005	DISMANTLE & REFIX UNDERCARRIAGE FRONT LHS AND REAR LHS TO FACILITATE REPAIR	600.00	?
8 ZZ/006	TRANSFER FRONT LHS AND REAR LHS DOOR MECHANISM	400.00	/
9 ZZ/007	TO CONDUCT WATER SEEPAGE TEST	100.00	50
10 ZZ/008	SUNDRIES	80.00	30
11 ZZ/009	TO SUPPLY AND REPLACE FRONT LHS AND REAR LHS TYRE		?
TOTAL LABOUR CHARGES		8992.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ7742C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	ARM ASSY F LH ?	20202FL030	138.20			
2	LINK ASSY R TRG ?	20250FL001	119.74			
3	LINK ASSY R LAT R ?	20250FL040	154.80			
4	ARM ASSY R UPR LH ?	20252SG011	432.00			
5	STRUT COMPL F LH ?	20310FL090	424.98			
6	MOUNT STRUT F ?	20320FL000	83.12			
7	SHOCK ABS COMPL R ?	20365FL110	207.54			
8	MOUNT SHOCK ABS R ?	20370FL000	92.23			
9	VALVE TPMS ASSY X2 / n/c	28103FL000	336.60			
10	HOUSING F LH ?	28313FL030	209.90			
11	DRV SFT ASSY F 92 ?	28321FL030	984.53			
12	HUB UNIT COMPL F ?	28373FL010	460.80			
13	HOUSING ASSY R ALLH ?	28411FL050	507.60			
14	DRV SFT ASSY R 75152 ?	28421FL020	945.65			
15	HUB UNIT COMPL R ?	28473FL020	234.00			
16	FENDER F XUV LH X R	57120FL0709P	207.54			
17	BUMPER PUNCHING F / CUT	57702FL310	446.40			
18	BRKT CORNER F FHILH ?	57707FL010	36.00			
19	BRKT SD F XUV LH ?	57707FL050	7.20			
20	COVER FOG F XUV LH / CUT	57731FL092	46.30			
21	PNL COMPL DR F LH / 07	60009FL0509P	920.00			
22	PNL COMPL DR R WLH / 07	60409FL0519P	888.00			
23	TAPE DR SASH F F LH / n/c	90422FL010	10.80			
24	TAPE DR SASH F M LH / n/c	90422FL030	10.80			
25	TAPE DR SASH R M WLH / n/c	90422FL050	7.50			

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	GARNISH AY FENDERLH / CUT	91112FL130	140.00			
27	GARNISH AY R QTR LH / CUT	91112FL150	140.00			
28	RIM GT EDTN 18" CAP P/N LPHGT28821VA011	LPHGT28100FL18	(Fm LH & Rear LH) 2pc	\$800 x 2	1600.00	cut
29	FRONT UNDER SPOILER GT-ML X	LPHGT96020HQ4			1032.00	
30	SIDE UNDER SPOILER GT LH-ML / CUT	LPHGT96032HQ4-LH			660.00	
SUB TOTAL			8192.23	0.00	3292.00	0.00
LESS DISCOUNT ( NETT-20 %)			1638.46	0.00	0.00	0.00
GRAND TOTAL			6553.77	0.00	3292.00	0.00
OVERALL TOTAL			9845.77			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED



SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMQ7742C

TOTAL LABOUR CHARGES	8992.00
TOTAL SPARE PARTS CHARGES	9845.77
GRAND TOTAL	18837.77 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE :  
LIABILITY :  
REMARKS :

Sten (LKK)  
15/9/21, 10.30am  
8322 8813

nil PL

8 dys

P/P

Ry Bel sy

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: