

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG21009619/R1TF3E2

**Date:** 29/10/2021

### REFERENCE

|                   |                                |                  |            |                  |
|-------------------|--------------------------------|------------------|------------|------------------|
| Insured/Claimant: | Pang Kay Siang (Feng Jiaxiang) | Policy No:       | 1000917637 |                  |
| Date of Loss:     | 12/09/2021                     | Nature of Claim: | OD         | Claim No: 262520 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                |             |             |
|-----------------------------|--------------------------------|-------------|-------------|
| Reg No:                     | SLM373M                        |             |             |
| Make & Model:               | HONDA VEZEL, 1.5 X SENSING (A) | Engine No:  | L15B4406942 |
| Reg. Date:                  | 20/03/2017 (Man. Year: 2016)   | Chassis No: | RU11206942  |
| Colour:                     | Brown                          | Odometer:   | 132866 km   |
| Engine Capacity:            | 1496 cc                        |             |             |
| Market Value/New Car Price: | S\$61,000.00                   |             |             |
| Sum Insured (S\$):          | Market Value/New Car Price     |             |             |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/60 R16  | Rear Tyre Size:  | 215/60 R16  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                      | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                               | 10,025.30        | 5,244.10        | 4,781.20        | 47.69        |
| Miscellaneous Items                 | 0.00             | 0.00            | 0.00            |              |
| Labour                              | 665.00           | 620.00          | 45.00           | 6.77         |
| Paintwork Labour                    | 715.87           | 715.87          | 0.00            | 0.00         |
| Towing                              | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>11,406.17</b> | <b>6,579.97</b> | <b>4,826.20</b> | <b>42.31</b> |
| <b>- Excess (S\$)</b>               | <b>500.00</b>    | <b>500.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>10,906.17</b> | <b>6,079.97</b> | <b>4,826.20</b> | <b>44.25</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>763.43</b>    | <b>425.60</b>   | <b>337.83</b>   | <b>44.25</b> |
| <b>Nett Amount (S\$)</b>            | <b>11,669.60</b> | <b>6,505.57</b> | <b>5,164.03</b> | <b>44.25</b> |

### INSPECTION

|                             |            |                   |                                                                                                      |
|-----------------------------|------------|-------------------|------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 14/09/2021 | Present Location: | Automotive Repair Centre Pte Ltd (HQ)                                                                |
| Date Inspected:             | 14/09/2021 | Inspected At:     | Automotive Repair Centre Pte Ltd (HQ)<br>38 Woodlands Industrial Park E1, #05-18<br>Singapore 757700 |
| Estimated Period of Repair: | 5.0 days   |                   |                                                                                                      |

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                 |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 29 Oct 2021)                   |
| <b>Parts:</b>        | M1-SUV                                                                                                                                                                       | HONDA VEZEL 1.5 X SENSING (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                               |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLM373M)                                                                                                                                     |                                                                 |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                 |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                 |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition   | Repairer's | Amount    |
|-----|-----|----------|---------------------------------------|-------------|------------|-----------|
| 1   | 1   | NA       | <b>*BONNET</b><br>(WCP)               | Bent        | 450.00 F   | *450.00 F |
| 2   | 1   | NA       | <b>*BONNET INSUL CLIPX10</b><br>(WCP) | Necessary   | 20.00 F    | *20.00 F  |
| 3   | 1   | NA       | <b>*BONNET LOCK</b><br>(WCP)          | Serviceable | 75.00 F    | *- F      |
| 4   | 1   | NA       | <b>*CONDENSER</b><br>(WCP)            | Bent        | 370.00 F   | *370.00 F |
| 5   | 1   | NA       | <b>*FRONT BUMPER</b><br>(WCP)         | Deformed    | 370.00 F   | *370.00 F |
| 6   | 1   | NA       | <b>*FRONT PANEL CPL</b><br>(WCP)      | Serviceable | 400.00 F   | *- F      |
| 7   | 1   | NA       | <b>*FRONT SPOILER</b><br>(WCP)        | Scratched   | 140.00 F   | *140.00 F |
| 8   | 1   | NA       | <b>*FRT BUMPER CLIP X 10</b><br>(WCP) | Necessary   | 20.00 F    | *20.00 F  |
| 9   | 1   | NA       | <b>*FRT BUMPER SUPPORT</b><br>(WCP)   | Cracked     | 180.00 F   | *180.00 F |
| 10  | 1   | NA       | <b>*FRT TOWING EYE COVER</b><br>(WCP) | Scratched   | 12.00 F    | *12.00 F  |
| 11  | 1   | NA       | <b>*GRILLE</b><br>(WCP)               | Cracked     | 210.00 F   | *210.00 F |
| 12  | 1   | NA       | <b>*GRILLE BADGE</b><br>(WCP)         | Missing     | 18.00 F    | *18.00 F  |
| 13  | 1   | NA       | <b>*GRILLE CVR CLIP X 10</b><br>(WCP) | Necessary   | 20.00 F    | *20.00 F  |
| 14  | 1   | NA       | <b>*L/BONNET HINGE</b><br>(WCP)       | Bent        | 33.00 F    | *33.00 F  |
| 15  | 1   | NA       | <b>*L/BONNET SEAL</b><br>(WCP)        | Necessary   | 15.00 F    | *15.00 F  |
| 16  | 1   | NA       | <b>*L/BONNET SEAL</b><br>(WCP)        | Necessary   | 15.00 F    | *15.00 F  |
| 17  | 1   | NA       | <b>*L/BUMPER CORNER BRKT</b><br>(WCP) | Serviceable | 12.00 F    | *- F      |
| 18  | 1   | NA       | <b>*L/F AIR DUCT</b><br>(WCP)         | Serviceable | 30.00 F    | *- F      |
| 19  | 1   | NA       | <b>*L/F HEADLAMP CPL</b><br>(WCP)     | Serviceable | 985.00 F   | *- F      |
| 20  | 1   | NA       | <b>*L/F UPP BUMPER BRKT</b><br>(WCP)  | Cracked     | 12.00 F    | *12.00 F  |
| 21  | 1   | NA       | <b>*L/GRILLE TRIM</b><br>(WCP)        | Cracked     | 50.00 F    | *50.00 F  |
| 22  | 1   | NA       | <b>*L/RAD-GRILLE BRACKET</b><br>(WCP) | Necessary   | 24.00 F    | *24.00 F  |
| 23  | 1   | NA       | <b>*L/UPP RADIATOR BRKT</b><br>(WCP)  | Serviceable | 10.00 F    | *- F      |
| 24  | 1   | NA       | <b>*L/WING MOULDING</b><br>(WCP)      | Cracked     | 55.00 F    | *55.00 F  |
| 25  | 1   | NA       | <b>*LOWER FRONT GRILLE</b><br>(WCP)   | Cut         | 55.00 F    | *55.00 F  |
| 26  | 1   | NA       | <b>*R/BONNET HINGE</b><br>(WCP)       | Bent        | 33.00 F    | *33.00 F  |
| 27  | 1   | NA       | <b>*R/BONNET SEAL</b><br>(WCP)        | Necessary   | 15.00 F    | *15.00 F  |

| No.                            | Qty | Part No. | Particulars                                          | Condition     | Repairer's | Amount    |
|--------------------------------|-----|----------|------------------------------------------------------|---------------|------------|-----------|
| 28                             | 1   | NA       | <b>*R/BOONET SEAL</b><br>(WCP)                       | Necessary     | 15.00 F    | *15.00 F  |
| 29                             | 1   | NA       | <b>*R/BUMPER CORNER BRKT</b><br>(WCP)                | Cracked       | 12.00 F    | *12.00 F  |
| 30                             | 1   | NA       | <b>*R/F AIR DUCT</b><br>(WCP)                        | Deformed      | 30.00 F    | *30.00 F  |
| 31                             | 1   | NA       | <b>*R/F HEADLAMP CPL</b><br>(WCP)                    | Cracked       | 985.00 F   | *985.00 F |
| 32                             | 1   | NA       | <b>*R/F UPP BUMPER BRKT</b><br>(WCP)                 | Cracked       | 12.00 F    | *12.00 F  |
| 33                             | 1   | NA       | <b>*R/RAD-GRILLE BRACKET</b><br>(WCP)                | Cracked       | 24.00 F    | *24.00 F  |
| 34                             | 1   | NA       | <b>*R/UPP RADIATOR BRKT</b><br>(WCP)                 | Serviceable   | 10.00 F    | *- F      |
| 35                             | 1   | NA       | <b>*R/WING MOULDING</b><br>(WCP)                     | Cracked       | 55.00 F    | *55.00 F  |
| 36                             | 1   | NA       | <b>*RADAR MILLIMETERWAVE</b><br>(WCP)                | Serviceable   | 2,160.00 F | *- F      |
| 37                             | 1   | NA       | <b>*RADAR WAVE BRACKET</b><br>(WCP)                  | Serviceable   | 450.00 F   | *- F      |
| 38                             | 1   | NA       | <b>*RAD GRILLE BRACKET</b><br>(WCP)                  | Cracked       | 24.00 F    | *24.00 F  |
| 39                             | 1   | NA       | <b>*RAD GRILLE COVER</b><br>(WCP)                    | Scratched     | 170.00 F   | *170.00 F |
| 40                             | 1   | NA       | <b>*RADIATOR</b><br>(WCP)                            | Bent          | 865.00 F   | *865.00 F |
| 41                             | 1   | NA       | <b>*UP/CVR RADIAT GRILLE</b><br>(WCP)                | Cracked       | 50.00 F    | *50.00 F  |
| 42                             | 1   | NA       | <b>*WASHER RESERVOIR</b><br>(WCP)                    | Serviceable   | 60.00 F    | *- F      |
| 43                             | 1   | NA       | <b>*4 LITRES COOLANT COOLANT 4L</b>                  | Necessary     | 35.00 FS   | *35.00 FS |
| 44                             | 1   | NA       | <b>*CHECK/RECTIFY WIRING CHECK WIRING</b>            | Necessary     | 20.00 FS   | *20.00 FS |
| 45                             | 1   | NA       | <b>*CHECK/SYNC FRT RADAR SYNC FRT RADAR</b>          | Not Necessary | 150.00 FS  | *- FS     |
| 46                             | 1   | NA       | <b>*FRONT LICENSE PLATE LICENSE PLATE</b>            | Cracked       | 35.00 FS   | *35.00 FS |
| 47                             | 1   | NA       | <b>*REFILL A/C GAS REFILL A/C GAS</b>                | Necessary     | 80.00 FS   | *60.00 FS |
| <b><u>Supplementary #1</u></b> |     |          |                                                      |               |            |           |
| 48                             | 1   |          | <b>*HORN (HIGH)</b><br>(WCP)                         | Distorted     | 30.00 F    | *30.00 F  |
| 49                             | 1   |          | <b>*A/C PIPE RECEIVE</b><br>(WCP)                    | Bent          | 110.00 F   | *110.00 F |
| 50                             | 1   |          | <b>*RADIATOR SHROUD LH</b><br>(WCP)                  | Cracked       | 90.00 F    | *90.00 F  |
| 51                             | 1   |          | <b>*AMBIENT SENSOR BRACKET CLIP</b><br>(WCP)         | Cracked       | 12.00 F    | *12.00 F  |
| 52                             | 1   |          | <b>*RADIATOR LOWER MOUNTING CUSHION X 2</b><br>(WCP) | Necessary     | 30.00 F    | *30.00 F  |

F=Franchise part. S=SpcNett.

|                                                  |                  |                 |
|--------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                          | <b>9,143.00</b>  | <b>4,781.00</b> |
| <b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b> | 882.30           | 463.10          |
| <b>Total Parts (\$\$)</b>                        | <b>10,025.30</b> | <b>5,244.10</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------|----------|-----------------|-----------------|
| <b><u>Paintwork Labour</u></b>  |                               |          |                 |                 |
| 1                               | Total Paint Labour            | New      | 500.00          | 500.00          |
| 2                               | Total Paint Materials         | New      | 215.87          | 215.87          |
| <b><u>Labour Items</u></b>      |                               |          |                 |                 |
| 3                               | Total Panel/Mechanical Labour | New      | 665.00          | 620.00          |
| <b>Gross Labour Cost (\$\$)</b> |                               |          | <b>1,380.87</b> | <b>1,335.87</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >