

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI21009623/KTCN2**Date:** 21/09/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ001903
Claimant Vehicle No :	SHD364J	Insured Vehicle No :	GBD8249C
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	M2104194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD364J	Engine No:	M9R8839C003029
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC282738
Reg. Date:	17/05/2016 (Man. Year: 2015)	Odometer:	578865 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,415.81	1,892.37	1,523.44	44.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	890.00	6,690.00	88.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,995.81	2,782.37	8,213.44	74.70
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	10,995.81	2,250.00	8,745.81	79.54
+ GST 7.00/7.00% (S\$)	769.71	157.50	612.21	79.54
Nett Amount (S\$)	11,765.52	2,407.50	9,358.02	79.54

INSPECTION

Date of Assignment:	20/09/2021	
Date Inspected:	13/09/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2021)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD364J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	-	*747.20 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	-	*- FL
3	1		*BUMPER BEAM FRT	Repair	663.70 FL	-	*- FL
4	1		*BUMPER BRACKET KIT FRT RH	Distorted	101.40 FL	-	*101.40 FL
5	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	-	*743.60 FL
6	1		*WIPER RESERVOIR	Serviceable	179.60 FL	-	*- FL
7	1		*FENDER PANEL FRT RH	Buckled	437.10 FL	-	*437.10 FL
8	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	-	*- FL
9	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	-	*- FS
10	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
11	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*- FS
12	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*- FS
13	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*- FS
14	1		*BUMPER CLIP FRT	Necessary	85.00 FS	-	*66.00 FS
15	1		*FENDER CLIP	Not Necessary	65.00 FS	-	*- FS
16	1		*FENDER LINER CLIP	Not Necessary	60.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,761.68	2,095.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	345.87	202.93
Total Parts (\$\$)	3,415.81	1,892.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$)			7,580.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >